

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance Management)
Singapore 068897

Our File No: CS6/AIS22012896/DVY3M4**Date:** 12/07/2023**REFERENCE**

Insured/Claimant: LIM WEE LEE, GERALD Policy No: SP2001262085-01
Date of Loss: 22/12/2022 Nature of Claim: OD Claim No: 202222009054/SL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDU8118J**
Make & Model: MAZDA 6, 2.0 SEDAN EXECUTIVE EU6 (A) Engine No: PE21103358
Reg. Date: 30/04/2018 (Man. Year: 2018) Chassis No: JM6GL1071J0147205
Colour: Red Odometer: 89672 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$85,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,291.70	6,417.40	2,874.30	30.93
Miscellaneous Items	115.00	15.00	100.00	86.96
Labour	1,590.00	1,030.00	560.00	35.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,996.70	7,462.40	3,534.30	32.14
- Excess (\$\$)	0.00	600.00	-600.00	
(\$\$)	10,996.70	6,862.40	4,134.30	37.60
+ GST 7.00/8.00% (\$\$)	769.77	548.99	220.78	28.68
Nett Amount (\$\$)	11,766.47	7,411.39	4,355.08	37.01

INSPECTION

Date of Assignment: 23/12/2022 Present Location: Wah Hong Motors & Credit Pte Ltd (HQ)
Date Inspected: 27/12/2022 Inspected At: Wah Hong Motors & Credit Pte Ltd (HQ)
Estimated Period of Repair: 4.0 days 38 Toh Guan Road East, #01-57, Enterprise Hub
Singapore 608581

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2023)
Parts:	143	MAZDA 6 2.0 SEDAN EXECUTIVE EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDU8118J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Bonnet (WCP)	Bent	850.00 F	*850.00 F
2	1		*Bonnet hinges LH/RH @2*\$50 (WCP)	Not Necessary	100.00 F	*- F
3	1		*Front bumper (WCP)	Distorted	1,750.00 F	*1,750.00 F
4	1		*Front bumper sponge (WCP)	Torn	55.00 F	*55.00 F
5	1		*Front bumper reinforcement (WCP)	Not Necessary	230.00 F	*- F
6	1		*Front bumper top panel (WCP)	Distorted	280.00 F	*280.00 F
7	1		*Center grille (WCP)	Cracked	90.00 F	*90.00 F
8	1		*Center grille Moulding 1 set 8 pieces (WCP)	Damaged	350.00 F	*350.00 F
9	1		*Center grille lower chrome RH/LH @2*\$80 (WCP)	O/S Cracked/ N/S Not Necessary	160.00 F	*80.00 F
10	1		*Front reverse sensor @4*\$105 (WCP)	Damaged(1Piece Only)	420.00 F	*105.00 F
11	1		*Head lamp LH/RH @2*\$1700 (WCP)	O/S Cracked/ N/S Not Necessary	3,400.00 F	*1,700.00 F
12	1		*Radiator top garnish (WCP)	Cracked	75.00 F	*75.00 F
13	1		*Radiator top panel (WCP)	Not Necessary	95.00 F	*- F
14	1		*Horn RH (WCP)	Not Necessary	55.00 F	*- F
15	1		*Center grille lower chrome base garnish LH/RH @2*\$38 (WCP)	O/S Damaged/ N/S Not Necessary	76.00 F	*38.00 F
Supplementary #1						
16	1		*Support Panel (WCP)	Cracked	260.00 F	*260.00 F
17	1		*Top Support Panel (WCP)	Bent	70.00 F	*70.00 F
18	1		*Front bumper Top clips @8*\$2.50 (WCP)	Necessary	20.00 F	*20.00 F
19	1		*Front bumper Top rivets @6*\$3.50 (WCP)	Necessary	21.00 F	*21.00 F
20	1		*Support Top panel rivets @6*\$3.00 (WCP)	Necessary	18.00 F	*18.00 F
21	1		*Logo badge base garnish (WCP)	Mtg Broken	40.00 F	*40.00 F
22	1		*Center grille logo badge (WCP)	Cracked	32.00 F	*32.00 F

F=Franchise part.

Sub Total (S\$)	8,447.00	5,834.00
+ Margin on L,N Items 10.00/10.00% (S\$)	844.70	583.40
Total Parts (S\$)	9,291.70	6,417.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Center Grille (Clips) Not Necessary	30.00	0.00
2	1	Front bumper Clips Necessary	35.00	15.00
Supplementary #1				
3	1	Coolant Not Necessary	50.00	0.00
Sub Total (S\$)			115.00	15.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	800.00	500.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	600.00	500.00
3	To remove and refix Front reverse sensor wiring system and head lamp at accident damaged area and check for all electrical proper function	New	90.00	30.00
Supplementary #1				
Labour Items				
4	To remove/refix and replace air-con condenser, pipes, vacuum and recharging gas.	New	100.00	0.00
Gross Labour Cost (S\$)			1,590.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >