5/18/23, 2:32 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIS22012897/UPA3Q2

18/05/2023 Date:

**REFERENCE** 

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP0001048320 **Claimant Vehicle** 

EN3232U **Insured Vehicle No:** SME6192J No:

Date of Loss: 19/12/2022 Nature of Claim: TP Claim No: 202222009057

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: EN3232U

BMW 318I, 1.5 LED NAV SHAD. LIGHT (A) F2681784B38B15A Make & Model: Engine No: Reg. Date: 16/11/2017 (Man. Year: 2017) Chassis No: WBA8E36070NU81197

Colour: White Odometer: 66359 km

**Engine Capacity:** 1499 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 225/40 R18 Rear Tyre Size: Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,201.10	622.06	1,579.04	71.74
Miscellaneous Items		0.00	0.00	0.00	
Labour		940.00	320.00	620.00	65.96
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	3,141.10	942.06	2,199.04	70.01
	+ GST 8.00/8.00% (S\$)	251.29	75.36	175.93	70.01
	Nett Amount (S\$)	3,392.39	1,017.42	2,374.97	70.01
	+ Car Rental (2.0 x S	\$100.00/day) (S\$)	200.00		
	+ Do	c/Search Fee (S\$)	2.00		
		Nett Liability (S\$)	1,219.42		

**INSPECTION** 

Date of Assignment: 22/12/2022

Progressive Car Care Pte Ltd (HQ) Date Inspected: 13/03/2023 Inspected At:

Blk 3022A Ubi Road 1, #01-45/46

Singapore 408716

Estimated Period of Repair: 2.0 days

MARCUS CHUA **CHEW HSIAO TONG** Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

## Reference

5/18/23, 2:32 PM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 May 2023)

Parts: 143 BMW 318I 1.5 LED NAV SHAD. LIGHT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for EN3232U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP -LH	Broken	654.80 FL	*654.80 FL
2	1		*REAR BUMPER	Repair	1,300.55 FL	*-FL
3	2		*REAR BUMPER SIDE HOLDER -LH/RH	Not Necessary	311.60 FL	*-FL
4	10		*REAR BUMPER CLIPS	Not Necessary	50.00 FL	*- FL
F=Fra	nchise	part. L=ListIte	mDisc.	Sub Total (S\$)	2,316.95	654.80
			- List Item Discount on L	· · · · · ·	115.85	32.74
				Total Parts (S\$)	2,201.10	622.06
			Report was unsubmitted during th	is print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	our Items						
1	TO KNOCK OUT DENTS ,REMOVE REPLACE ACCIDENT F	PARTS New	400.00	100.00			
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	500.00	200.00			
3	TO CHECK WIRING	New	40.00	20.00			
	G	Gross Labour Cost (S\$)	940.00	320.00			
	Report was unsubmitted during this print-out.						

< END OF ESTIMATES >