



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4758X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT BUMPER COVER	TO REPAIR SEE LABOUR	499.90	-
1	FRT BUMPER CENTRE GRILLE	NOT NECESSARY	318.80	-
1	FRT RAD GRILLE	NOT NECESSARY	88.00	-
1	FRT BUMPER TOW COVER	NOT NECESSARY	28.38	-
1	FRT GRILLE EMBLEM	NECESSARY	43.80	43.80
1	FRT NO PLATE EXT GARNISH	DEFORMED	99.00	99.00
2	FRT BUMPER SIDE RETAINER RH / LH @\$77.00	NOT NECESSARY	154.00	-
	LESS 25% DISCOUNT		-307.97	-35.70
			923.91	107.10
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE & W/HOLDER (SN)	BENT	55.00	55.00
			55.00	55.00
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT BUMPER COVER.		550.00	350.00
	SPRAY PAINTING CHARGE.		500.00	250.00
	CHECK WIRING.	NOT NECESSARY	60.00	-
	TUFF COAT.	NOT NECESSARY	60.00	-
			1,170.00	600.00
GRAND TOTAL			2,148.91	762.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				600.00

Report Ref No. NS/INC22012900/Tvce2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.