

ASS. REC. BY:

REF: CC4/ASM 22012902/DPK3

ASSIGNMENT

COB May 2026
Yr Regn: 2016 May

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLC 4289A

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish c.c. 1794

Colour: Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 248757 T/Radio: Insured / Std / NI / NA

Eng/No: 28R1727372

C/No: ZGE 206030067

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: -11-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Arivo

Front Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 16/12/2022 D.O.I. 27/12/2022

Survey held at Goh Lee the AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rn

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>AXA SH 80945</u>
	<u>MV 38K</u>
	<u>LTA 28.3K</u>
	<u>DL 9.7K.</u>
<u>15/2/23</u>	<u>Insured LP 4,300 - with 5 days of work</u>

Date/Time, File Pass to?

: Prel. Report
 : Final Report

1) Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

Report Format: _____

Revision: _____

Goh Lee Hwa Automobile Pte Ltd
Block 5033 Ang Mo Kio Industrial Park 2
#01-255
Singapore 569536

SLC4289A Toyota Wish

1	1	Front right door panel <i>HH</i>	\$	1,465.20	X
2	1	Rear bumper assy <i>cut / missing broken</i>	\$	1,259.20	✓ 645.20
3	1	Rear bumper reflector <i>HH</i>	\$	89.90	X
4	1	Rear bumper right retainer <i>SH</i>	\$	44.30	X
5	1	Rear bumper right bracket <i>HH</i>	\$	43.10	X
6	1	Rear right taillamp <i>HH</i>	\$	640.50	X
7	1	Rear right door panel <i>SH</i>	\$	1,261.40	✓
8	1	Rear right door regulator with motor <i>HH</i>	\$	493.50	X
9	1	Rear right door weatherstrip <i>SH</i>	\$	182.60	X
10	1	Rear right door outer handle <i>HH</i>	\$	127.20	X
11	1	Rear right door lock mechanism <i>HH</i>	\$	225.80	X
12	1	Rear right door checker linkage <i>HH</i>	\$	161.30	X
13	1	Rear right door inner board <i>HH</i>	\$	478.20	X
14	2	Rear right door hinges <i>HH</i>	\$	130.10	X
15	1	Rear right door glass assy <i>HH</i>	\$	388.80	X
16	1	Rear right door glass outer moulding <i>SH</i>	\$	176.40	X
17	1	Rear right suspension assy <i>HH</i>	\$	860.60	X
18	1	Rear right wheel hub bearing <i>distorted</i>	\$	272.30	✓
19	1	Rear axle beam <i>distorted</i>	\$	1,800.10	✓ 1736.40
20	1	Rear right fender <i>SH</i>	\$	1,482.30	X
21	1	Rear right fender inner cowling <i>HH</i>	\$	128.70	X
22	1	Rear right quarter glass moulding <i>HH</i>	\$	128.90	X
23	1	Rear right sill panel <i>SH</i>	\$	998.70	X
24	1	Rear windscreen glass moulding <i>HH</i>	\$	280.20	X
25	1	Rear right 'B' pillar <i>HH</i>	\$	1,459.10	X
			\$	14,578.40	
		less 25%	\$	3,644.60	
			\$	10,933.80	
		<u>Special Nett Items</u>			
1	10	Rear bumper clips <i>SH</i>	\$	60.00	20/-
2	1	Rear no plate with garnish <i>HH</i>	\$	100.00	X
3	1	Rear right fender sealant <i>HH</i>	\$	100.00	X
4	1	Rear windscreen glass sealant <i>HH</i>	\$	100.00	X
5	1	Rear right wheel rim <i>SH</i>	\$	750.00	✓ 500/-
6	1	Rear right tyre <i>SH</i>	\$	350.00	X
7	1	Rear right quarter glass sealant <i>HH</i>	\$	100.00	X
8	1	Rear right side skirting <i>SH</i>	\$	1,400.00	X
9	1	Rear right side skirting sealant <i>HH</i>	\$	100.00	X
10	10	Rear right side skirting clips <i>HH</i>	\$	60.00	X
11	6	Rear right fender inner cowling clips <i>HH</i>	\$	40.00	X
12	8	Rear right door inner board clips <i>HH</i>	\$	40.00	X
			\$	3,200.00	
		Total parts	\$	14,133.80	

Goh Lee Hwa Automobile Pte Ltd
Block 5033 Ang Mo Kio Industrial Park 2
#01-255
Singapore 569536

SLC4289A Toyota Wish

1	Labour for panel beating, cut, weld, straighten rear right affected area and replace rear right damaged parts.	\$ 1,400.00	800/-
2	To putty and spray painting rear right portion.	\$ 1,400.00	800/-
3	To check rear lighting and wiring.	\$ 50.00	HW
4	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00	80/-
5	To apply anti rust proofing to rear right affected area.	\$ 140.00	40/-
6	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00	HW
7	To remove and install rear right undercarriage parts.	\$ 350.00	150/-
8	To balance rear right wheel.	\$ 50.00	20/-
9	To conduct wheel alignment.	\$ 120.00	60/-
10	To remove and install rear right door lock mechanism.	\$ 80.00	60/-
11	To check front right and rear right door central locking for function.	\$ 80.00	HW
12	To transfer front right door glass to new door.	\$ 80.00	HW
13	To transfer rear right door glass to new door.	\$ 80.00	HW
14	To remove and install rear right door regulator with motor assy.	\$ 80.00	HW
15	To remove and install rear right quarter glass.	\$ 80.00	HW
16	Towing service.	\$ 100.00	HW
		Total labour :	\$ 4,370.00

2010.00

27/12/2022 @ 1700 hrs

HLA Antenna

2 HSM

5 days

(Signature)

2 KK Ant

(Signature)

Total parts : \$ 14,133.80

Total labour : \$ 4,370.00

Total repair cost : \$ 18,503.80

5,466.47
4s 4,300/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

NAME
ADDRESS

Home Tel.:
VIN:
Registration:
Technician:
Mileage:
Time Printed 28.12.22 10:24 AM

TOYOTA WISH

Front : Left

Actual	BEFORE	Specified Range
-0°28'		-1°15' 0°15'
2°53'		2°20' 3°50'
-0°11'		-0°05' 0°05'
9°12'		10°35' 12°05'
8°44'		9°20' 12°20'

Front : Right

Actual	BEFORE	Specified Range
-0°51'		-1°15' 0°15'
3°20'		2°20' 3°50'
0°08'		-0°05' 0°05'
16°50'		10°35' 12°05'
16°00'		9°20' 12°20'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front

	Actual	BEFORE	Specified Range
Cross Camber	0°23'		-0°45' 0°45'
Cross Caster	-0°27'		-0°45' 0°45'
Cross SAI	-7°38'		
Total Toe	-0°03'		-0°11' 0°11'
Cross Turn Diff.			

Rear : Left

Actual	BEFORE	Specified Range
-1°48'		-2°00' -1°00'
0°17'		-0°02' 0°12'

Rear : Right

Actual	BEFORE	Specified Range
-0°59'		-2°00' -1°00'
0°20'		-0°02' 0°12'

Camber
Toe

Rear

	Actual	BEFORE	Specified Range
Cross Camber	-0°49'		-0°30' 0°30'
Total Toe	0°37'		-0°03' 0°25'
Thrust Angle	-0°01'		
Axle Offset	0mm		

SLC 4289 A