

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22012908/RQY3Q2**Date:** 06/01/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MQ000609	
Claimant Vehicle No :	SH6755Z	Insured Vehicle No :	SMY1601Z	
Date of Loss:	27/12/2022	Nature of Claim:	TP	Claim No: M2207391

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH6755Z	Engine No:	2ZRS043820
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Chassis No:	JTDKBB3FU203557196
Reg. Date:	30/05/2017 (Man. Year: 2017)	Odometer:	611958 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,341.02	506.13	834.89	62.26
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	750.00	600.00	150.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,102.02	1,117.13	984.89	46.85
Approved Total (Overridden) (S\$)		900.00		
(S\$)	2,102.02	900.00	1,202.02	57.18
+ GST 7.00/7.00% (S\$)	147.14	63.00	84.14	57.18
Nett Amount (S\$)	2,249.16	963.00	1,286.16	57.18

INSPECTION

Date of Assignment:	27/12/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	28/12/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2023)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH6755Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER ASSY	Deformed	586.18 FL	*586.18 FL
2	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*FRT BUMPER LOWER GRILLE	Not Necessary	193.18 FL	*- FL
4	1		*FRT NUMBER PLATE	Cracked	50.00 F	*50.00 F
5	1		*FRT BUMPER FOG LAMP LH	Not Necessary	920.00 FL	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	1,771.36 658.18
					- List Item Discount on L Items 25.00/25.00% (S\$)	430.34 152.05
					Total Parts (S\$)	1,341.02 506.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT	New	300.00	250.00
3	CHECK WIRING	New	50.00	0.00
Gross Labour Cost (\$\$)			750.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >