

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EQI22012909/RVY3M4**Date:** 12/01/2023REFERENCE

Handling Insurer:	EQ Insurance Company Ltd	Policy No:	DMPPHQ22-001949
Claimant Vehicle No :	SHA4519U	Insured Vehicle No :	SFL6236M
Date of Loss:	24/12/2022	Nature of Claim:	TP
		Claim No:	DM22HO02261

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA4519U	Engine No:	D4DFU561955
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMHU098227
Reg. Date:	11/01/2017 (Man. Year: 2016)	Odometer:	762896 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,821.40	3,245.56	4,575.84	58.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,680.00	2,710.00	970.00	26.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,501.40	5,955.56	5,545.84	48.22
Approved Total (Overridden) (S\$)		4,750.00		
(S\$)	11,501.40	4,750.00	6,751.40	58.70
+ GST 7.00/7.00% (S\$)	805.10	332.50	472.60	58.70
Nett Amount (S\$)	12,306.50	5,082.50	7,224.00	58.70

INSPECTION

Date of Assignment:	28/12/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	28/12/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	8.0 days		

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jan 2023)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA4519U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR RH	Repair	2,707.70 FL	*- FL
2	1		*REAR DOOR RH	Repair	2,416.80 FL	*- FL
3	1		*REAR FENDER RH	Bent	2,171.40 FL	*2,171.40 FL
4	1		*REAR BUMPER	Scratched	553.00 FL	*553.00 FL
5	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
6	1		*REAR WHEEL CAP RH	Deformed	217.20 FL	*217.20 FL
7	1		*ROCKER PANEL GARNISH RH	Deformed	732.80 FL	*732.80 FL
8	1		*REAR WHEEL RIM RH	Repair	325.30 FL	*- FL
9	1		*REAR WESTLAKE TYRE RH	Not Necessary	216.00 F	*- F
10	1		*FRT DOOR COMFORTDELGRO RH	Necessary	75.00 F	*75.00 F
11	1		*REAR DOOR ZIG RH	Necessary	80.00 F	*80.00 F
12	1		*REAR WINDSCREEN MOULDING	Necessary	51.80 FL	*51.80 FL
13	2		*REAR WINDSCREEN SEALANT	Necessary	92.00 F	*92.00 F
						F=Franchise part. L=ListItemDisc.
Sub Total (S\$)					9,661.00	3,995.20
- List Item Discount on L Items 20.00/20.00% (S\$)					1,839.60	749.64
Total Parts (S\$)					7,821.40	3,245.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	1,120.00
2	SPRAY PAINTING	New	1,500.00	1,250.00
3	TUFF KOTE	New	200.00	60.00
4	TRANSFER DOORS	New	240.00	0.00
5	WHEEL ALIGNMENT	New	120.00	60.00
6	R/I REAR WINDSCREEN	New	150.00	120.00
7	R/I REVERSE SENSORS	New	120.00	40.00
8	R/I UPHOLSTERY ETC	New	150.00	60.00
Gross Labour Cost (S\$)			3,680.00	2,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >