



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 345Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT LID	TO REPAIR SEE LABOUR	886.00	-
1	REAR BOOT LID HYUNDAI LOGO	NOT NECESSARY	32.90	-
1	REAR BOOT LID AVANTE EMBLEM	NOT NECESSARY	32.50	-
2	REAR BOOT LID LAMP L/R @\$126.30	SERVICEABLE	252.60	-
1	REAR BUMPER	BUCKLED	582.20	582.20
2	REAR BUMPER SIDE HOLDER L/R @\$42.30	SERVICEABLE	84.60	-
2	REAR BUMPER BRACKET L/R @\$78.30	TO REPAIR SEE LABOUR	156.60	-
1	REAR BUMPER REINFORCEMENT	CRACKED	286.20	286.20
1	REAR BUMPER INNER FOAM	CRACKED	141.40	95.20
1	REAR BOOT LID MECHANISM LOCK	TO REPAIR SEE LABOUR	168.00	-
1	REAR BOOT WEATHERSTRIP	SERVICEABLE	118.30	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	485.10	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	89.30	-
	LESS 20% DISCOUNT		-663.14	-192.72
			2,652.56	770.88
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	45.00	45.00
1	SET TOP GARNISH CLIPS (SN)	NOT NECESSARY	35.00	-
1	SET REVERSE SENSOR (SN)	SHORTED	250.00	200.00
			330.00	245.00
<u>LABOUR</u>				
	TO REMOVE & REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS.		80.00	10.00
	TO REMOVE & REINTAL UPHOLSTERY ,TRIM GARNISHES TO FACILITATE REPAIRS .		80.00	50.00
	TO REMOVE,TRANSFER BOOT LID COMPONENTS.	NOT NECESSARY	80.00	-
	TO REMOVE,REPAIR & REPLACE DAMAGED BODYPARTS ,REALIGN BODYWORK AND WHERE CONSISTENT TO THE ACCIDENT .		600.00	400.00

Report Ref No. CS/AGI22012911/Kny3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS.		600.00	400.00
	TO REMOVE & RENEW REVERSE SENSOR .		100.00	50.00
	RUST PROOFING ON AFFECTED PORTIONS.	NOT NECESSARY	100.00	-
			1,640.00	910.00
GRAND TOTAL			4,622.56	1,925.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CS/AGI22012911/Kny3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.