

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|--|-----------------|------|-----------------------|--|
| | LIBERTY INSURA | NCE PTE LTD | R | ef: | CS/LIP22012912/Uny3e2 | |
| | 51 CLUB STREET LIBERTY HOUSES | , #03-00 SINGAPORE 069428 | D | ate: | 13/01/2023 | |
| | | | С | ode: | LIP | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SLC 4297B | Veh. Inspected | | SKX 7537R | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | AVS23/0013 | Excess (\$) | | 0.00 | |
| | Assign From | ANDY SEAH | Assign Date | | 28/12/2022 | |
| 2. | Vehicle Particulars & Condition | | | | | |
| | Make & Model | TOYOTA COROLLA ALTIS (A) | c.c | | 1598 | |
| | Engine No. | HIDDEN | Year of Reg. | | | |
| | Chassis No. | MR053REH104537305 | Colour | | SILVER | |
| | Odometer | 134474 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 205/55 R16 | PIRELLI | | 6 mm | |
| | L/H Front Tyre | 205/55 R16 | PIRELLI | | 6 mm | |
| | R/H Rear Tyre | 205/55 R16 | PIRELLI | | 6 mm | |
| | L/H Rear Tyre | 205/55 R16 | PIRELLI | | 6 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 24/12/2022 | Inspection Date | | 28/12/2022 | |
| | Survey held at | ZOOM AUTOWERKS PTE LTD | | | | |
| | | 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130 | | | | |
| 5a. | Remarks | | | | | |
| | A)REGISTRATION DATE: 28 DEC 2015 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | | Estimate Days of Repair | | | | |
| | ESTIMATED NOR | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days | | | | |
| | | | | | | |