

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012916/UNP3Q2**Date:** 13/01/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00238782101

Claimant Vehicle No : SLP6076R **Insured Vehicle No :** SKX8375J

Date of Loss: 23/12/2022 Nature of Claim: TP Claim No: SNM22D209285/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP6076R**

Make & Model: HONDA VEZEL, 1.5 (A) Engine No: LEB5908341

Reg. Date: 12/06/2017 (Man. Year: 2016) Chassis No: RU31208331

Colour: White Odometer: 74400 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,030.24	3,271.04	3,759.20	53.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	1,790.00	1,290.00	41.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,110.24	5,061.04	5,049.20	49.94
Approved Total (Overridden) (\$\$)		4,000.00		
(\$\$)	10,110.24	4,000.00	6,110.24	60.44
+ GST 8.00/8.00% (\$\$)	808.82	320.00	488.82	60.44
Nett Amount (\$\$)	10,919.06	4,320.00	6,599.06	60.44

INSPECTION

Date of Assignment: 27/12/2022

Date Inspected: 05/01/2023 Inspected At: Cas Garage Pte Ltd (HQ)
No.1, Kaki Bukit Ave 6, #02-22 Autobay
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jan 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP6076R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,068.10 FL	*912.60 FL
2	1		*TAILGATE OUTER GARNISH W LOGO	Not Necessary	321.80 FL	*- FL
3	1		*TAILGATE EMBLEM -VEZEL	Necessary	79.50 FL	*58.00 FL
4	1		*TAILGATE EMBLEM -HYBRID	Necessary	79.50 FL	*79.50 FL
5	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	152.40 FL	*- FL
6	2		*TAILGATE LAMP	Not Necessary	760.60 FL	*- FL
7	1		*TAILGATE LOCK	Twisted	224.00 FL	*174.00 FL
8	1		*TAILGATE WEATHERSTRIP	Twisted	145.20 FL	*105.20 FL
9	1		*TAILGATE INNER TRIM -BOTTOM	Cracked	231.10 FL	*231.10 FL
10	1		*SET TAILGATE GLASS MOULDING	Necessary	147.50 FL	*68.10 FL
11	1		*REAR BUMPER	Dented	553.10 FL	*553.10 FL
12	2		*REAR BUMPER SIDE RETAINER	Not Necessary	83.00 FL	*- FL
13	2		*REAR BUMPER REFLECTOR	Cracked	357.00 FL	*302.00 FL
14	1		*END PANEL	Dented	470.20 FL	*470.20 FL
15	1		*END PANEL TOP GARNISH	Twisted	86.60 FL	*86.60 FL
16	1		*REAR BUZZER	Not Necessary	107.30 FL	*- FL
17	1		*SPARE TYRE PANEL	Repair	720.30 FL	*- FL
18	1		*SPARE TYRE TOP BOARD	Torn	298.80 FL	*298.80 FL
19	1		*SPARE TYRE TOOL BOX SPONGE	Cracked	228.00 FL	*228.00 FL
20	1		*REAR UNDERCARRIAGE UNDER COVER	Twisted	84.10 FL	*84.10 FL
21	2		*TAILLAMP	Not Necessary	973.40 FL	*- FL
22	2		*TAILLAMP LOWER GARNISH	Not Necessary	385.60 FL	*- FL
23	2		*REAR FENDER INNER TRIM	Not Necessary	468.20 FL	*- FL
24	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	30.00 FS	*30.00 FS
25	1		*TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
26	1		*REAR NUMBER PLATE W CASING	Not Necessary	60.00 FS	*- FS
27	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
28	1		*REAR BUMPER SENSORS	Shorted	300.00 FS	*200.00 FS
29	1		*SET END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
30	1		*END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,635.30	4,001.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,605.06	730.26
Total Parts (\$\$)	7,030.24	3,271.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT /STRAIGHTEN /REALIGN ACCIDENT AFFECTED AREAS	New	1,200.00	600.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	800.00
3	TO TUFF COAT ON AFFECTED AREAS	New	80.00	60.00
4	TO CONDUCT WIRING CHECK AND REPAIR	New	60.00	20.00
5	TO DISMANTLE /TRANSFER TAILGATE COMPONENTS	New	150.00	60.00
6	TO REMOVE/REFIX TAILGATE GLASS	New	150.00	120.00
7	TO CONDUCT WATER LEAKAGE TESTING	New	60.00	0.00
8	TO REMOVE/REFIX REAR INTERIOR UPHOLSTERY ,SEAT ,SEAT BELT	New	120.00	80.00
9	TO REMOVE/REFIX REVERSE SENSOR AND DISTANCE SETTING	New	60.00	50.00
Gross Labour Cost (\$\$)			3,080.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >