

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012919/KQP3Q2**Date:** 19/01/2023**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00023872205

**Claimant Vehicle
No :** SLG5765P**Insured Vehicle
No :** GY3409X

Date of Loss: 22/12/2022

Nature of Claim: TP

Claim
No: SNM22D209273/C02/TAYHP**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLG5765P**

Make & Model: HONDA VEZEL, 1.5 X CVT (A)

Engine No: L15B4403636

Reg. Date: 05/10/2016 (Man. Year: 2016)

Chassis No: RU11203632

Colour: Metallic Black

Odometer: 128425 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 3 mm

Rear Left Side: Dunlop 2 mm

Front Right Side: Dunlop 3 mm

Rear Right Side: Dunlop 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,265.98	5,702.48	10,563.50	64.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,010.00	1,930.00	3,080.00	61.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,275.98	7,632.48	13,643.50	64.13
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	21,275.98	6,100.00	15,175.98	71.33
+ GST 8.00/8.00% (S\$)	1,702.08	488.00	1,214.08	71.33
Nett Amount (S\$)	22,978.06	6,588.00	16,390.06	71.33

INSPECTION

Date of Assignment: 27/12/2022

Date Inspected: 28/12/2022 Inspected At:

My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ)
60 Jalan Lam Huat, Carros Centre #05-21
Singapore 737869

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2023)
Parts: M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLG5765P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,542.00 FL	*953.00 FL
2	1		*TAILGATE OUTER GARNISH	Cracked	421.00 FL	*321.00 FL
3	2		*TAILGATE NUMBER PLATE LAMP	Serviceable	108.00 FL	*- FL
4	2		*TAILGATE REFLECTOR	Cracked	842.20 FL	*842.20 FL
5	1		*TAILGATE INNER TRIM	Mtg Cracked	358.00 FL	*312.00 FL
6	4		*TAILGATE GLASS MOULDING	Necessary (1 PCS ONLY)	672.00 FL	*164.00 FL
7	1		*TAILGATE INNER HANDLE	Dented	68.50 FL	*68.50 FL
8	1		*TAILGATE WIPER MOTOR	Serviceable	512.00 FL	*- FL
9	1		*TAILGATE LOCK	Jammed	224.00 FL	*224.00 FL
10	1		*TAILGATE LOWER LOCK	Repair	24.00 FL	*- FL
11	1		*TAILGATE WEATHERSTRIP (50%)	Dented / Distorted	123.20 FS	*77.00 FS
12	1		*TAILGATE EMBLEM VEZEL	Necessary	56.00 FL	*56.00 FL
13	2		*TAILGATE STOPPER	Serviceable	36.00 FL	*- FL
14	2		*TAILLAMP	Cracked	1,194.40 FL	*1,021.20 FL
15	1		*TAILLAMP SIDE GARNISH	O/S Buckled	144.00 FL	*72.00 FL
16	2		*TAILLAMP PANEL	Repair	430.00 FL	*- FL
17	1		*REAR BUMPER	Bent	863.50 FL	*762.70 FL
18	1		*REAR BUMPER SIDE UPPER	O/S Buckled	900.00 FL	*195.00 FL
19	1		*REAR BUMPER SIDE RETAINER	O/S Distorted	110.00 FL	*55.00 FL
20	2		*REAR BUMPER REFLECTOR	Serviceable	116.00 FL	*- FL
21	2		*REAR FENDER	Repair	2,108.00 FL	*- FL
22	2		*REAR FENDER INNER COWLING	Serviceable	374.00 FL	*- FL
23	1		*REAR WHEEL ARCH GARNISH	O/S Buckled	716.00 FL	*166.00 FL
24	1		*REAR FENDER INNER TRIM	N/S Serviceable /O/SMtgCracked	1,096.00 FL	*366.00 FL
25	1		*REAR END PANEL	Bent	630.00 FL	*585.00 FL
26	1		*REAR END PANEL TOP GARNISH	Dented	189.00 FL	*162.00 FL
27	1		*REAR FLOOR PANEL	Repair	1,224.00 FL	*- FL
28	1		*REAR FLOOR PANEL TOP BOARD	Serviceable	300.00 FL	*- FL
29	1		*REAR FLOOR PANEL UNDER COVER	Serviceable	254.00 FL	*- FL
30	1		*REAR FLOOR PANEL TOOLS BOX SPONGE	Serviceable	258.00 FL	*- FL
31	2		*REAR AIR VENTILATION DUCT	Serviceable	96.00 FL	*- FL
32	1		*REAR REVERSE SENSOR	Shorted	216.00 FS	*200.00 FS
33	1		*REAR EXHAUST PIPE	Repair	1,221.00 FL	*- FL
34	1		*REAR EXHAUST INSULATOR	Serviceable	154.00 FL	*- FL
35	10		*REAR BUMPER CLIPS	Necessary	65.00 FS	*65.00 FS
36	6		*REAR BUMPER SIDE UPPER CLIP	Not Necessary	39.00 FS	*- FS
37	1		*TAILGATE SEALANT	Necessary	80.00 FS	*40.00 FS
38	12		*TAILGATE INNER TRIM CLIP	Not Necessary	78.00 FS	*- FS
39	1		*TAILGATE WINDSCREEN SEALANT	Repeated	80.00 FS	*- FS
40	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	50.00 FS	*30.00 FS
41	10		*TAILGATE PROTECTOR CLIPS	Not Necessary	65.00 FS	*- FS
42	1		*SET TAILGATE COMPANY LOGO	Necessary	500.00 FS	*60.00 FS
43	4		*TAILLAMP CLIP	Necessary	32.00 FS	*32.00 FS
44	15		*REAR FENDER INNER COWLING CLIP	Not Necessary	97.50 FS	*- FS
45	1		*REAR FENDER INNER TRIM CLIPS	O/S Necessary	78.00 FS	*39.00 FS

Report was unsubmitted during this print-out.

1/19/23, 2:59 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	10		*REAR WHEEL ARCH GARNISH CLIP	Necessary (5 PCS ONLY)	65.00 FS	*65.00 FS
47	4		*REAR END PANEL TOP GARNISH CLIPS	Necessary	34.00 FS	*34.00 FS
48	1		*REAR END PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
49	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
50	1		*REVERSE CAMERA	Serviceable	350.00 FS	*- FS
51	1		*REVERSE SENSOR	Repeated	220.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)						19,714.30 6,967.60
- List Item Discount on L Items 20.00/20.00% (\$\$)						3,448.32 1,265.12
Total Parts (\$\$)						16,265.98 5,702.48
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,800.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	800.00
3	WIRING CHECK	New	80.00	20.00
4	REMOVE AND REFIX REAR WINDSCREEN	New	150.00	120.00
5	CONDUCT LEAKAGE TEST ON TAILGATE	New	80.00	20.00
6	TUFF KOTE	New	250.00	60.00
7	REMOVE AND REFIX EXHAUST TAILPIPE	New	250.00	0.00
8	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY TO FACILITATE REPAIR	New	350.00	60.00
9	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	250.00	50.00
Gross Labour Cost (S\$)			5,010.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >