

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22012920/UVY3Q2
Date: 17/01/2023

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00077822203	
Claimant Vehicle No :	SLB3070A	Insured Vehicle No :	SLX6637E	
Date of Loss:	23/12/2022	Nature of Claim:	TP	Claim No: SNM22D209261/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB3070A
Make & Model:	MAZDA 2, 1.5 HATCHBACK L SP.6EAT (A)
Reg. Date:	31/03/2016 (Man. Year: 2015)
Colour:	Grey
Engine Capacity:	1496 cc
Engine No:	P520336621
Market Value/New Car Price:	N/A
Chassis No:	JM6DJ2HAA01100693
Sum Insured (S\$):	Market Value/New Car Price
Odometer:	117804 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,474.19	4,543.28	3,930.91	46.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,260.00	1,100.00	2,160.00	66.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,734.19	5,643.28	6,090.91	51.91
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	11,734.19	4,500.00	7,234.19	61.65

INSPECTION

Date of Assignment:	16/01/2023	
Date Inspected:	28/12/2022	Inspected At: 15 KAKI BUKIT ROAD 4 #01-53 SINGAPORE 417808
Estimated Period of Repair:	4.0 days	Repairer: Zoom Autowerks Pte Ltd (HQ)

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2023)
Parts:	144	MAZDA 2 1.5 HATCHBACK L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB3070A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Not Necessary	985.80 FL	*- FL
2	1		*FRONT HEADLAMP -LH	Scratched/ Cracked	1,417.60 FL	*1,417.60 FL
3	1		*FRONT HEADLAMP LOWER BRACKET	Not Necessary	83.80 FL	*- FL
4	1		*FRONT GRILLE CHROME MOULDING	Not Necessary	285.00 FL	*- FL
5	1		*FRONT BUMPER	Torn	888.80 FL	*888.80 FL
6	1		*FRONT BUMPER FOG LAMP	Not Necessary	200.40 FL	*- FL
7	1		*FRONT BUMPER FOG LAMP COVER	Scratched	150.30 FL	*68.90 FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	448.50 FL	*- FL
9	1		*FRONT BUMPER SIDE RETAINER (N/S)	Cracked	80.30 FL	*45.00 FL
10	1		*FRONT FENDER -LH	Dented / Bent	556.90 FL	*481.00 FL
11	1		*FRONT FENDER INNER SHIELD	Torn	200.60 FL	*166.00 FL
12	1		*FRONT WHEEL RIM -LH	Warped / Bent	800.30 FL	*800.30 FL
13	1		*FRONT WHEEL HUB	Bent	400.30 FL	*305.00 FL
14	1		*FRONT WHEEL BEARING	Necessary	388.80 FL	*288.00 FL
15	1		*FRONT SHOCK ABSORBER	Bent	485.50 FL	*351.40 FL
16	1		*FRONT KNUCKLE ARM	Bent	800.80 FL	*375.60 FL
17	1		*FRONT LOWER ARM	Bent	535.00 FL	*366.50 FL
18	1		*FRONT TIE ROD	Not Necessary	140.40 FL	*- FL
19	1		*SET FRONT BUMPER CLIP	Necessary	55.00 FS	*50.00 FS
20	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	55.00 FS	*50.00 FS
21	1		*FRONT TYRE	Serviceable	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,359.10	5,654.10
- List Item Discount on L Items 10.00/20.00% (\$)	884.91	1,110.82
Total Parts (\$)	8,474.19	4,543.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	20.00
2	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	250.00	120.00
3	TO CONDUCT WHEEL ALIGNMENT	New	180.00	80.00
4	TO APPLY UNDERCOATING	New	150.00	30.00
5	PANEL BEATING	New	1,400.00	450.00
6	TO RESPRAY PAINTING ON THE AFFECTED AREAS	New	1,200.00	400.00
Gross Labour Cost (\$\$)			3,260.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >