

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22012921/RQP3Q2**Date:** 27/06/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00245192201
<b>Claimant Vehicle No :</b>	SND3456L	<b>Insured Vehicle No :</b>	SMK7640U
Date of Loss:	19/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D209148/C02/KHONGLH

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SND3456L</b>	Engine No:	F122K815B48B20A
Make & Model:	BMW X3, 2.0 (A)	Chassis No:	WBATY120909H86823
Reg. Date:	16/12/2021 (Man. Year: 2021)	Odometer:	11261 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	245/50 R19	Rear Tyre Size:	245/50 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,410.50	3,495.95	914.55	20.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,753.00	3,559.00	194.00	5.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>8,163.50</b>	<b>7,054.95</b>	<b>1,108.55</b>	<b>13.58</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>653.08</b>	<b>564.40</b>	<b>88.68</b>	<b>13.58</b>
<b>Nett Amount (S\$)</b>	<b>8,816.58</b>	<b>7,619.35</b>	<b>1,197.23</b>	<b>13.58</b>

**INSPECTION**

Date of Assignment:	27/12/2022	
Date Inspected:	12/01/2023 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 26 Jun 2023)
<b>Parts:</b> M1-SUV	BMW X3 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SND3456L)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS	
2	1		*TAIL PANEL	Not Necessary	542.20 FS	*- FS	
3	1		*REAR BUMPER CARRIER	Bent	800.10 FS	*800.10 FS	
4	1		*REAR BUMPER BOTTOM REINFORCEMENT	Cracked	83.95 FS	*83.95 FS	
5	1		*REAR UNDERRIDE GUARD (LUXURY LINE)	Not Necessary	323.55 FS	*- FS	
6	1		*REAR BUMPER PANEL PRIMED (X LINE PM)	Scratched	1,536.45 FS	*1,536.45 FS	
7	1		*REAR BUMPER CLADDING (PDC)	Scratched	740.50 FS	*740.50 FS	
8	1		*REAR BUMPER TOWING EYE COVER	Not Necessary	48.80 FS	*- FS	
9	1		*REAR UNDERRIDE GUARD (X LINE)	Cracked	254.95 FS	*254.95 FS	
					<b>Total Parts (S\$)</b>	<b>4,410.50</b>	<b>3,495.95</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RESPRAY REAR BUMPER AND AFFECTED AREA	New	1,038.00	986.00
2	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	0.00
3	TO REMOVE OLD PDC ASSEMBLY REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
4	TO CHECK ELECTRICAL	New	295.00	280.00
5	TO REPLACE REAR BUMPER PANEL ,REAR CARRIER ,REAR BOTTOM REINFORCEMENT REAR UNDERRIDE GUARD ,REAR CLADDING INCLUDE CARRYING OUT NECESSARY REPAIRS CAUSED BY THE ACCIDENT	New	2,125.00	2,125.00
<b>Gross Labour Cost (S\$)</b>			<b>3,753.00</b>	<b>3,559.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >