

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012932/RVP3E2**Date:** 18/01/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00240772200
Claimant Vehicle No :	SKX7489X	Insured Vehicle No :	SNG9792K
Date of Loss:	23/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D209304/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX7489X	Engine No:	CHH304767
Make & Model:	VOLKSWAGEN GOLF, 2.0 GTI (A)	Chassis No:	WVWZZZAUZKW111756
Reg. Date:	31/05/2019 (Man. Year: 2019)	Odometer:	48608 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,638.81	2,919.95	1,718.86	37.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,480.00	3,200.00	3,280.00	50.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,118.81	6,119.95	4,998.86	44.96
+ GST 8.00/8.00% (S\$)	889.50	489.60	399.90	44.96
Nett Amount (S\$)	12,008.31	6,609.55	5,398.76	44.96

INSPECTION

Date of Assignment:	28/12/2022		
Date Inspected:	30/12/2022	Inspected At:	Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2023)
Parts:	144	VOLKSWAGEN GOLF 2.0 GTI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX7489X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*INSCRIPTION BRIGHT CHROME REAR BOOT LID NAME PLATE - GTI	Not Necessary	97.17 FS	*- FS
2	1	*COVER FOR BUMPER PRIMED REAR BUMPER	Deformed	1,190.76 FS	*1,190.76 FS
3	1	*COVER FOR TOWING EYE PRIM	Not Necessary	34.83 FS	*- FS
4	1	*BUMPER REINFORCEMENT	Not Necessary	750.84 FS	*- FS
5	1	*ATTACHMENT STRIP BUMPER CTR BUMPER	Not Necessary	73.18 FS	*- FS
6	1	*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Not Necessary	43.33 FS	*- FS
7	1	*GUIDE PIECE RHR BUMPER BRACKET (UPPER)	Not Necessary	43.33 FS	*- FS
8	1	*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	43.33 FS	*- FS
9	1	*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Not Necessary	43.33 FS	*- FS
10	1	*SENSOR BRACKET	Necessary	14.79 FS	*14.79 FS
11	1	*SENSOR BRACKET	Necessary	14.79 FS	*14.79 FS
12	2	*SENSOR BRACKET	Necessary	28.58 FS	*28.58 FS
13	1	*SENSOR BRACKET	Necessary	14.29 FS	*14.29 FS
14	1	*SENSOR BRACKET	Necessary	14.93 FS	*14.93 FS
15	2	*SENSOR PRIMED	Not Necessary	380.36 FS	*- FS
16	2	*SEAL RING SATIN BLACK	Necessary	2.92 FS	*2.92 FS
17	1	*2K-PLASTIC ADHESIVE	Necessary	85.94 FS	*85.94 FS
18	1	*BONDING AGENT FOR PLASTIC	Necessary	68.85 FS	*68.85 FS
19	2	*LED LICENCE PLACE LIGHT	Not Necessary	128.14 FS	*- FS
20	1	*REFLECTOR RH	Not Necessary	81.02 FS	*- FS
21	1	*REAR APRON ATTACHMENT WIT BUMPER LOWER BODY KIT	Cracked	1,340.79 FS	*1,340.79 FS
22	1	*ADHESIVE KIT FOR AERODYNA	Necessary	63.31 FS	*63.31 FS
23	1	*REAR NUMBER PLATE	Bent	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **4,638.81** **2,919.95**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	2,520.00	840.00
4	SPRAY PAINT	New	3,200.00	1,600.00
Gross Labour Cost (\$\$)			6,480.00	3,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >