



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 2009U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT WHEEL FENDER	TO REPAIR SEE LABOUR	168.00	-
1	FRONT WINDSHIELD	CRACKED	288.00	288.00
1	FRONT WINDSHIELD BRACKET	NOT NECESSARY	342.00	-
1	FRONT COWLING	NOT NECESSARY	110.00	-
2	FRONT SIDE COWLING @\$190.00	CRACKED	380.00	380.00
1	FRONT COWLING LOWER GARNISH (BLACK)	CUT	185.00	185.00
1	HEADLAMP	CRACKED	755.00	755.00
1	FRONT LH SIGNAL LAMP	NOT NECESSARY	95.00	-
1	BALANCER LH	CUT	55.00	55.00
1	FRONT LH HAND LEVER	CUT	48.00	48.00
1	FRONT LH WING MIRROR	CUT	65.00	65.00
1	HANDLE BAR	NOT NECESSARY	180.00	-
1	FRONT FORK ASSY	BENT	680.00	680.00
1	FRONT FORK UNDER BRACKET	NECESSARY	220.00	220.00
1	STEERING CONE & BEARING	NECESSARY	120.00	120.00
1	SIDE COWLING LH	NOT NECESSARY	105.00	-
1	STEP PANEL GARNISH LH	CUT	370.00	370.00
1	REAR LH FOOTREST	NOT NECESSARY	60.00	-
1	REAR LH FOOTREST BRACKET	NOT NECESSARY	120.00	-
1	ENGINE TOP COVER	CUT	350.00	350.00
	LESS 10% DISCOUNT		-469.60	-351.60
			4,226.40	3,164.40
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	NECESSARY	15.00	15.00
1	FORK OIL (SN)	NECESSARY	30.00	30.00
1	STEP PANEL GARNISH TOP PLATE (SN)	NOT NECESSARY	50.00	-
1	REAR BOX (SN)	CUT	280.00	200.00
1	REAR BOX BRACKET (SN)	NOT NECESSARY	250.00	-

Report Ref No. CS/AGI22012933/Avy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET STICKERS (SN)	NECESSARY	50.00	50.00
			675.00	295.00
	<u>LABOUR</u>			
	PANEL BEATING, REMOVE AND REFIT PARTS. INCLUSIVE OF THE REPAIR OF FRONT WHEEL FENDER.	NOT NECESSARY	400.00	200.00
	SPRAY PAINTING TO AFFECTED AREA.		400.00	200.00
	WIRING CHECK.		50.00	30.00
	TO STRAIGHTEN CHASSIS BODY.		250.00	-
	1,100.00	430.00		
GRAND TOTAL			6,001.40	3,889.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,100.00

Report Ref No. CS/AGI22012933/Avy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.