

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD	Ref	f:	CS3/LPC22012937/Kqy3e2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Dar	te:	05/01/2023	
			Co	de:	LPC2	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YN 1337C	Veh. Inspected		SKR 4956R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/22/23/VC05/026765	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		28/12/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA ESTIMA (A)	c.c		2362	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	ACR507065296	Colour		METALLIC LIGHT GREEN	
	Odometer	180136 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/50 R18	GITI		8 mm	
	L/H Front Tyre	225/50 R18	GITI		8 mm	
	R/H Rear Tyre	225/50 R18	GITI		8 mm	
	L/H Rear Tyre	225/50 R18	GITI		8 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRONT PORTION.				
5.	General Information					
	Accident Date	25/12/2022	Inspect Date / Tim	е	29/12/2022 (09:48 AM)	
	Survey held at	THIAM HENG HUAT PTE LTD				
		176 SIN MING DRIVE #05-14 SINGAPORE 575721				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22012937/Kqy3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

1

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser