

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S2M045Q9 Date: 17th Jan 2023

Our Ref: CS3/ASM22006331/Aqp3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01 Axa Tower Singapore 068811 (The Motor Claims Department)

Attn: Khor Saw Theng

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBK 9537C INSURED VEHICLE: SHC 1504X

ACCIDENT DATE: 29/06/2022

We thank you for your instruction on 20/12/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBK 9537C from M/s J&M Consultancy Pte Ltd.
- b) Singapore Accident Statement of Vehicles GBK 9537C and SHC 1504X.
- c) Final Repair Bill of GBK 9537C from M/s A-Tec Automotive Pte Ltd.
- d) Colour damaged vehicle photographs of GBK 9537C.

Pre-Repair Inspection Date: 04/07/2022 at M/s 8 Kaki Bukit Ave 4 Premier @ KB #04-20, Repairer: A-Tec Automotive Pte Ltd.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : GBK 9537C

Make & Model : Toyota Hiace Van Turbo 4DR AT

Year of Registration : 2021

Chassis Number : JTFHT02P800251246

Engine Capacity : 2982 cc

- 2. We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.