

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/III22012941/AQY3Q2**Date:** 27/03/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549\_03  
**Claimant Vehicle No :** FBT1316D **Insured Vehicle No :** GBJ2664U  
 Date of Loss: 26/12/2022 Nature of Claim: TP Claim No: MFL2023D0000033

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **FBT1316D**  
 Make & Model: HONDA ADV150, 149cc ABS CVT Engine No: KF61E1040102  
 Reg. Date: 19/11/2021 (Man. Year: 2021) Chassis No: MH1KF6110MK040018  
 Colour: Red Odometer: 14820 km  
 Engine Capacity: 149 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 110/80 R14 Rear Tyre Size: 130/70 R13  
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 5,294.00          | 3,434.90          | 1,859.10          | 35.12         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 1,050.00          | 430.00            | 620.00            | 59.05         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>6,344.00</b>   | <b>3,864.90</b>   | <b>2,479.10</b>   | <b>39.08</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>3,000.00</b>   |                   |               |
| <b>Nett Amount (S\$)</b>                 | <b>6,344.00</b>   | <b>3,000.00</b>   | <b>3,344.00</b>   | <b>52.71</b>  |

**INSPECTION**

Date of Assignment: 28/12/2022  
 Date Inspected: 09/01/2023 Inspected At: Jec Auto Service (HQ)  
 1 KAKI BUKIT AVENUE 6 #02-11, Autobay @ Kaki Bukit  
 Singapore 417883  
 Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

|                      |  |  |
|----------------------|--|--|
| <b>Part Source:</b>  | (Last Synchronised: 27 Mar 2023)   |  |
| <b>Parts:</b>        | N/A  | HONDA ADV150 149cc ABS CVT (Model not available in database) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                            |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for FBT1316D)  |  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

**Recommended Parts**

| No. | Qty | Part No. | Particulars                 | Condition     | Repairer's | Amount     |
|-----|-----|----------|-----------------------------|---------------|------------|------------|
| 1   | 1   |          | *FRONT NUMBER PLATE STICKER | Torn          | 15.00 FS   | *15.00 FS  |
| 2   | 1   |          | *FRONT WINDSHIELD           | Cracked       | 288.00 F   | *288.00 FL |
| 3   | 1   |          | *FRONT WINDSHIELD BRACKET   | Cracked       | 342.00 F   | *342.00 FL |
| 4   | 1   |          | *FRONT CENTRE COWLING       | Repair        | 110.00 F   | *- FL      |
| 5   | 1   |          | *FRONT COWLING SIDE         | N/S Cracked   | 390.00 F   | *190.00 FL |
| 6   | 1   |          | *HEADLAMP ASSY              | Cracked       | 755.00 F   | *755.00 FL |
| 7   | 1   |          | *FRONT WHEEL FENDER         | Repair        | 168.00 F   | *- FL      |
| 8   | 1   |          | *FRONT FORK ASSY            | Bent          | 680.00 F   | *680.00 FL |
| 9   | 1   |          | *FRONT FORK UNDERBRACKET    | Damaged       | 220.00 F   | *220.00 FL |
| 10  | 1   |          | *STEERING CONE AND BEARING  | Necessary     | 120.00 F   | *120.00 FL |
| 11  | 1   |          | *FRONT FORK OIL             | Necessary     | 30.00 FS   | *30.00 FS  |
| 12  | 1   |          | *BALANCER LH                | Cut           | 55.00 F    | *55.00 FL  |
| 13  | 1   |          | *FRONT LEVER LH             | Cut           | 48.00 F    | *48.00 FL  |
| 14  | 1   |          | *FRONT LH WING MIRROR       | Not Necessary | 85.00 F    | *- FL      |
| 15  | 1   |          | *FRONT LH SIGNAL LAMP       | Cut           | 95.00 F    | *95.00 FL  |
| 16  | 1   |          | *FRONT LH CRASH BAR         | Cut           | 245.00 F   | *245.00 FL |
| 17  | 1   |          | *REAR LH FOOTREST           | Not Necessary | 60.00 F    | *- FL      |
| 18  | 1   |          | *REAR ENGINE COVER (BLACK)  | Not Necessary | 210.00 F   | *- FL      |
| 19  | 1   |          | *REAR ENGINE COVER (SILVER) | Cut           | 168.00 F   | *168.00 FL |
| 20  | 1   |          | *REAR ENGINE TOP COVER      | Cut           | 350.00 F   | *350.00 FL |
| 21  | 1   |          | *SIDE COWLING LH            | Repair        | 125.00 F   | *- FL      |
| 22  | 1   |          | *REAR SEAT HANDLE LH        | Cut           | 155.00 F   | *155.00 FL |
| 23  | 1   |          | *REAR CONTAINER             | Not Necessary | 280.00 FS  | *- FS      |
| 24  | 1   |          | *REAR CONTAINER BRACKET     | Not Necessary | 250.00 FS  | *- FS      |
| 25  | 1   |          | *STICKERS                   | Necessary     | 50.00 FS   | *50.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|   |                 |                 |
|---|-----------------|-----------------|
| <b>Sub Total (\$)</b>                                   | <b>5,294.00</b> | <b>3,806.00</b> |
| <b>- List Item Discount on L Items 0.00/10.00% (\$)</b> | 0.00            | 371.10          |
| <b>Total Parts (\$)</b>                                 | <b>5,294.00</b> | <b>3,434.90</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                  | Particulars                             | Lab.Type | Repairer's                      | Amount        |
|---------------------|---|----------|---------------------------------|---------------|
| <b>Labour Items</b> |   |          |                                 |               |
| 1                   | LABOUR                                  | New      | 400.00                          | 200.00        |
| 2                   | SPRAY PAINTING                          | New      | 400.00                          | 200.00        |
| 3                   | WIRING                                  | New      | 50.00                           | 30.00         |
| 4                   | TO REPAIR AND STRAIGHTEN CHASSIS MEMBER | New      | 200.00                          | 0.00          |
|                     |   |          | <b>Gross Labour Cost (\$\$)</b> | <b>430.00</b> |

1,050.00

430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >