

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	INDIA INTERNATION	ONAL INSURANCE PL		Ref:	CS3/GRB22010810/Svy3e2-1	
	64 CECIL STREET #05-02 IOB BUILD	ING SINGAPORE 049711		Date:	06/01/2023	
				Code:	GRB	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLS 5273D	Veh. Inspected		GBE 4050D	
	Policy No.	D21MFL0000447_01	Coverage (\$)		0.00	
	Claim No.	MFL2022D0006564	Excess (\$)		0.00	
	Assign From	CARINE KEK	Assign Date		27/12/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA DYNA	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	KDY2318021471	Colour		WHITE	
	Odometer	278153 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195 R15C	ENERGY VAN		6 mm	
	L/H Front Tyre	195 R15C	ENERGY VAN		6 mm	
	R/H Rear Tyre	155 R13	ENERGY VAN		6 mm	
	L/H Rear Tyre	155 R13	ENERGY VAN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	26/10/2022	Inspection Date	е	31/10/2022	
	Survey held at	EVOLUTION96 AUTO PTE LTD				
		3020A UBI ROAD 1 #01-33 SINGAPORE 408714				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				