



## T & C AUTOMOBILE ASSESSORS

SOH BUAY CHAI  
C/O Ming Hua Auto Services  
Blk 160 Sin Ming Drive  
#02-16 Singapore 575722

Ref: TC/2019/0454

Date: 29/04/2019

### VEHICLE SURVEY REPORT

#### REFERENCE

Request By : Workshop , On Behalf Of Owner  
Date Of Request : 15/04/2019  
Date Of Accident : 13/04/2019  
Date Of Inspection : 16/04/2019  
Inspected At : Ming Hua Auto Services  
Blk 160 Sin Ming Drive  
#02-16 Singapore 575722

#### PARTICULARS OF VEHICLE

Vehicle Registration No.	: SMK1255M	Make & Model	: HONDA SHUTTLE HYBRID 1.5 AUTO
Year Make	: 2018	Colour	: GREY
Engine No.	: LEB7103336	Chassis No.	: GP72002518
Engine Capacity	: 1496 cc		

#### CONDITION OF VEHICLE AND TYRES

General condition	: Good	Mileage	: 6310
Brakes	: Serviceable	Modification	: None
steering	: Serviceable	handbrake	: Serviceable


<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>
Front RHS	BRIDGESTONE	185/60R15	8
Front LHS	BRIDGESTONE	185/60R15	8
Rear RHS	BRIDGESTONE	185/60R15	9
Rear LHS	BRIDGESTONE	185/60R15	9

#### DESCRIPTION OF DAMAGES

The vehicle sustained damages at the LH SIDE portion .  
(For information of damages , please refer to Parts / Labour / Photographs attached)

#### INSTRUCTION

This survey was conducted entirely on a "WITHOUT PREJUDICE" basis , and we have not authorised any repair .



Paper survey done by Store. Annex A

## T & C AUTOMOBILE ASSESSORS

### ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No : SMK1255M

Report No : TC/2019/0454

#### PARTS

S/NO	QTY	DESCRIPTION	CONDITION / REMARKS	REPAIRER'S ESTIMATES S\$	OUR ASSESSMENT S\$
1	1	Front Bumper	Cracked	1,332.00	1,332.00 1050 ✓
2	1	Front Bumper Lh Retainer	Necessary	97.50	97.50 ✓
3	12	Front Bumper Clip	Necessary	36.00	36.00 30 ✓
4	1	Front Lh Fender	Buckled	882.00	882.00 462 ✓
5	1	Front Lh Fender Innershield	Deformed	247.50	247.50 184 ✓
6	1	Emblem - Hybrid	Necessary	154.50	154.50 65 ✓
7	1	Front Lh Fender Extension Panel	Dent	849.00	849.00 X R
8	1	Lh Headlamp (no closed-up photo)	Glazed	2,820.00	2250 2,820.00 X NN ✓
9	1	Lh Wing Mirror With Stay	Broken	975.00	975.00 527 ✓
10	1	Lh Wing Mirror Glass	Reuse	270.00	0.00 X NN
11	1	Lh Wing Mirror Cover	Missing	247.50	247.50 85 ✓
12	1	Front Lh Door	Dent	1,575.00	1,575.00 1050 ✓
13	1	Front Lh Door Frame Sticker	Necessary	187.50	187.50 80 ✓
14	1	Front Lh Door Outer Handle	Respray	235.50	0.00 X NN
15	1	Rear Lh Door	Dent	1,875.00	1,875.00 X R
16	1	Rear Lh Door Frame Sticker	Necessary	202.50	202.50 X NN
17	1	Lh Side Skirt	Torn	880.50	880.50 535 ✓
18	1	Front Lh Wheel Cap	Glazed	253.50	253.50 150 ✓
19	1	Front Lh Shock Absorber	Bent	834.00	834.00 456 ✓
20	1	Front Lh Knuckle Arm	Bent	1,147.50	1,147.50 385 ✓
21	1	Front Lh Wheel Bearing	Necessary	679.50	679.50 225 ✓
22	1	Front Lh Lower Arm	Bent	798.00	798.00 X NN
				16,579.50	16,074.00 5381.50
Less : Discount 10%				-1,657.95	-1,607.40 -20%
Total :				14,921.55	14,466.60 4305.20

#### MISCELLANEOUS ITEMS

1	1	Front Lh Tyre	Glazed	180.00	160.00 X NN
Total :				180.00	160.00



# T & C AUTOMOBILE ASSESSORS

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No : SMK1255M

Report No : TC/2019/0454

### PANEL & MECHANICAL LABOUR

<u>S/NO</u>	<u>DESCRIPTION</u>	<u>REPAIRER'S ESTIMATES S\$</u>	<u>OUR ASSESSMENT S\$</u>
1	To remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	1,550.00	1,250.00 800
2	To check wirings and lightings.	60.00	40.00 30
3	To remove and install front rh suspension unit.	280.00	220.00 200X
4	To conduct wheel alignment .	75.00	75.00 ✓
5	To transfer door glass , trims and others related parts to new door.	220.00	160.00 80
Total :		2,185.00	1,745.00





# T & C AUTOMOBILE ASSESSORS

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No : SMK1255M

Report No : TC/2019/0454

### PAINT

Code : TWO COAT METALLIC

#### LABOUR COST - PAINT

##### DESCRIPTION

To applies body filler , sanding , applies primer coat , spray painting and clearcoat. And polish the affected portions.

##### REPAIRER'S ESTIMATES S\$

##### OUR ASSESSMENT S\$

900.00

700.00 650

Total :

900.00

700.00

#### MATERIAL COST - PAINT

##### DESCRIPTION

To supplies polyurethane paint, clear coat lacquer, primer, masking tape, cleaning solvent, 1200- and 2000-grit sandpaper, filler, and paint thinner.

##### REPAIRER'S ESTIMATES S\$

##### OUR ASSESSMENT S\$

400.00

300.00 250

Total :

400.00

300.00

7 days

2085

### FINAL CALCULATION

6390.20

L/S - 5112.16

= 5100

##### DESCRIPTION

##### REPAIRER'S ESTIMATES S\$

##### OUR ASSESSMENT S\$

Parts

14,921.55

14,466.60

Miscellaneous items

180.00

160.00

Panel &amp; Mechanical Labour

2,185.00

1,745.00

Paint Labour

900.00

700.00

Paint Material

400.00

300.00

Total Repair Cost :

18,586.55

17,371.60

### Remarks

The repairer has agreed to undertake the repair of S\$ 17,371.60 , with a repair period of 9 working days.

Surveyed By :

Lee Thiam Ming

