

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012947/KVP3E2
Date: 20/06/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00110832202
Claimant Vehicle No :	SLR5068K	Insured Vehicle No :	GBC9380D
Date of Loss:	23/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D209280/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR5068K	Engine No:	3A92UGB5940
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AHH006352
Reg. Date:	17/08/2017 (Man. Year: 2017)	Odometer:	99173 km
Colour:	Metallic Pearl White		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,403.70	4,402.62	5,001.08	53.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,870.00	2,160.00	710.00	24.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,273.70	6,562.62	5,711.08	46.53
Approved Total (Overridden) (S\$)		5,100.00		
Nett Amount (S\$)	12,273.70	5,100.00	7,173.70	58.45

INSPECTION

Date of Assignment:	30/12/2022	
Date Inspected:	29/12/2022	Inspected At: 60 Jalan Lam Huat #04-53 Singapore 737869
Estimated Period of Repair:	7.0 days	Repairer: Win Automotive Services (HQ)

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Jun 2023)	
Parts:	N/A	mitsubishi attrage 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR5068K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	700.00 FL	*700.00 FL
2	1		*REAR BUMPER SIDE RETAINER LH & RH	N/S Distorted	150.00 FL	*75.00 FL
3	1		*SET REAR BUMPER FASTENERS	Necessary	28.00 FL	*28.00 FL
4	1		*REAR BUMPER RH AND LH RETAINER GARNISH	N/S Distorted /O/S Serviceable	220.00 FL	*110.00 FL
5	1		*BOOTLID	Bent	950.00 FL	*721.00 FL
6	1		*BOOTLID WEATHERSTRIP (\$148.00) (50%)	Distorted / Dented	285.00 FN	*74.00 F
7	1		*BOOTLID CHROME GARNISH	Serviceable	255.00 FL	*- FL
8	1		*BOOTLID LOGO EMBLEM	Necessary	85.00 FL	*41.00 FL
9	1		*BOOTLID MITSUBISHI EMBLEM	Necessary	85.00 FL	*85.00 FL
10	1		*BOOTLID ATTRAGE EMBLEM	Necessary	85.00 FL	*38.00 FL
11	1		*BOOTLID INNER LOCK	Dented	220.00 FL	*220.00 FL
12	1		*BOOTLID LOCK STRIKER	Repair	48.00 FL	*- FL
13	1		*BOOTLID INNER TRIM	Serviceable	350.00 FL	*- FL
14	1		*BOOTLID INNER TRIM CLIPS	Necessary	28.00 FL	*28.00 FL
15	2		*RH & LH REAR AIR VENT	Serviceable	190.00 FL	*- FL
16	2		*RH & LH TAILLAMP	Mtg Cracked	780.00 FL	*670.80 FL
17	2		*RH & LH TAILLAMP LOWER BRACKET RETAINER	Serviceable	180.00 FL	*- FL
18	2		*SET RH & LH TAILLAMP FASTENERS	Necessary	35.00 FL	*35.00 FL
19	1		*REAR END PANEL	Bent	650.00 FL	*482.00 FL
20	1		*REAR END PANEL TOP GARNISH	Dented	255.00 FL	*78.00 FL
21	1		*REAR END PANEL TOP GARNISH FASTENERS	Necessary	28.00 FL	*28.00 FL
22	1		*SPARE TYRE PANEL	Repair	880.00 FL	*- FL
23	1		*SPARE TYRE PANEL BOARD	Serviceable	300.00 FL	*- FL
24	2		*RH & LH REAR FENDER INNER TRIM	Serviceable	580.00 FL	*- FL
25	2		*RH & LH REAR FENDER INNER TRIM FASTENERS	Not Necessary	56.00 FL	*- FL
26	2		*RH & LH REAR FENDER INNER SHIELD	Serviceable	265.00 FL	*- FL
27	2		*RH & LH REAR FENDER INNER SHIELD CLIPS	Not Necessary	35.00 FL	*- FL
28	1		*LH REAR FENDER	Buckled	780.00 FL	*780.00 FL
29	1		*REAR WINDSCREEN MOULDING	Necessary	155.00 FL	*112.00 FL
30	1		*REAR EXHAUST MUFFLER	Repair	950.00 FL	*- FL
31	1		*REAR EXHAUST MUFFLER MOULDING	Serviceable	85.00 FL	*- FL
32	1		*SPARE TYRE PANEL SEALANT	Not Necessary	60.00 FS	*- FS
33	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
34	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*30.00 FS
35	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
36	1		*REVERSE CAMERA	Shorted	300.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	10,373.00	4,825.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	940.80	423.18
- Nett Item Discount on N Items 10.00/0.00% (\$\$)	28.50	0.00

Total Parts (\$\$) 9,403.70 4,402.62

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.						
---	--	--	--	--	--	--

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT PARTS	New	1,000.00	900.00
2	SUPPLY PAINT MATERIAL AND NECESSARY ITEMS. TO RESPRAY REPLACED AND OTHER AFFECTED PANELS	New	1,000.00	900.00
3	REMOVE AND REINSTALL EXHAUST MUFFLER	New	80.00	0.00
4	STRAIGHTEN AND REALIGN CHASSIC MEMBER	New	250.00	0.00
5	TO REMOVE AND REINSTALL REAR SEAT UPHOLSTERY	New	80.00	60.00
6	TO CHECK WIRING SYSTEM FOR PROPER FUNCTIONS	New	30.00	20.00
7	REMOVE AND REINSTALL REVERSER SENSOR	New	80.00	50.00
8	TO CARRY OUT ANTI RUST TREATMENT	New	120.00	60.00
9	TO REMOVE AND REINSTALL REAR WINDSCREEN	New	150.00	120.00
10	TO REMOVE AND REINSTALL BOOTLID COMPONENTS	New	80.00	50.00
Gross Labour Cost (\$\$)			2,870.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >