

ASS. REC. BY:

REF:

C72 / 220129471Kv

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Caros 04-53

238H

Insured: GBC 9380D

Policy No. DMCVSNW00110832202

Claims No. SNM22D209280/C02/TANCHC


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SR 5068K

Yr Regn:

08.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit

Attaga

C.C.

1193

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

99173

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MMBSTA13A1H1 006352

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / STD / Rim / STD A/Rim or

Tyre Size:

F:

R:

195/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

23/12/22

D.O.I.

29/12/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 EM not ready

15/6 61 Rmp @ 5100k Cabs (red 7173.70, 58%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 19/6/23-typist

Days Of Repair: 7

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

Report Format: Merimen

Lump Sum / L.B. (\$ 5100

TOTAL

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO: SLR 50681

Not Withheld
 11 Bmp & 5100/hr
 Recovery After Paint
 7 days

Adjustment of Spare Parts Costs for Repairs

Item	Qty	Vehicle parts description	Condition / Remark	Estimated by workshop
1	1	rear bumper	Bu	700.00 ✓
2	2	rear bumper side retainer LH & RH	also dis	150.00 ✓
3	1set	rear bumper fasteners	na	28.00 ✓
4	2	rear bumper rh and lh retainer garnish	also dis	220.00 ✓
5	1	bootlid 721	Bu	950.00 ✓
7	1	bootlid weatherstrip 148	dis in	285.00 ✓
8	1	bootlid chrome garnish	in	255.00 X
9	1	bootlid logo emblem 41.00	na	85.00 ✓
10	1	bootlid mitsubishi emblem	na	85.00 ✓
11	1	bootlid attrage embem 38	na	85.00 ✓
12	1	bootlid inner lock	nd	220.00 ✓
13	1	bootlid lock striker	R	48.00 X
14	1	bootlid inner trim	in	350.00 X
15	1	bootlid inner trim clips	na	28.00 ✓
17	2	rh & lh rear air vent	in	190.00 X
18	2	rh & lh taillamp 0335.40	mgmt	780.00 ✓
19	2	rh & lh taillamp lower bracket retainer	in	180.00 X
20	2set	rh & lh taillamp fasteners	na	35.00 ✓
21	1	rear end panel 482	Bu	650.00 ✓
22	1	rear end panel top garnish 78	nd	255.00 ✓
23	1	rear end panel top garnish fasteners	na	28.00 ✓
24	1	spare tyre panel	R	880.00 X
25	1	spare tyre panel board	in	300.00 X
26	2	rh & lh rear fender inner trim	in	580.00 X
27	2	rh & lh rear fender inner trim fasteners	na	56.00 X
28	2	rh & lh rear fender inner sheild	in	265.00 X
29	2	rh & lh rear fender inner sheild clips	na	35.00 X
30	1	Lh rear fender	Bu	780.00 ✓
31	1	rear windscreen moulding 112	na	155.00 ✓
32	1	rear exhaust muffler	R	950.00 X
33	1	rear exhaust muffler moulding	in	85.00 X

Less 10%

9693.00

969.30

8723.70

Special nett item

1	spare tyre panel sealant	na	60.00 X
1	rear windscreen sealant	na	60.00 X
1	rear end panel sealant	na	60.00 X
1	reverse sensor	shan	200 ✓
1	reverse camera	shang	300 ✓

680.00

Adjustment of Labour Costs for Repairs

To remove and replaced damaged parts including straightening and repositioning replacement parts.	1000.00	900
Supply paint material and necessary items. To respray replaced and other affected panels.	1000.00	900
remove and reinstall exhaust muffler	nn 80.00	X
straighten and realign chassic member	nn 250.00	X
to remove and reinstall rear seat upholstery	80.00	60
To check wiring system for proper functions.	30.00	20
remove and reinstall reverser sensor	80.00	50
To carry out anti rust treatment.	120.00	60
to remove and reinstall rear windscreen	150.00	120
to remove and reinstall bootlid components	80.00	50

Total labour 2870.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before ~~after~~ spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: