

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT CS3/ASM22012951/Kqp3e2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER 05/01/2023 Date: SINGAPORE 068811 ATTN: OH VALE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHB 3084H** FBU 2125B Veh. Inspected Policy No. VFX/P2419140 Coverage (\$) 0.00 Claim No. S2M04FOO Excess (\$) 0.00 OH VALE **Assign Date** 28/12/2022 Assign From **Vehicle Particulars & Condition** 2. YAMAHA AEROX c.c 155 Make & Model HIDDEN 2022 Engine No. Year of Reg. MH3SG6410NJ185557 **BLACK** Chassis No. Colour 4050 KM Odometer Steering **JAMMED JAMMED** STANDARD ALLOY RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 110/80 R14 **IRC** 7 mm L/H Front Tyre mm 140/70 R14 **IRC** R/H Rear Tyre 7 mm L/H Rear Tyre mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. 5. **General Information** 27/11/2022 03/01/2023 (01:02 PM) Inspect Date / Time Accident Date TMS BIKES PTE LTD Survey held at 61 Woodlands Industrial Park E9 E9 Premium, #01-06 Singapore 757047 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

Report Ref No. CS3/ASM22012951/Kqp3e2

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000-\$12,000

Estimate Days of Repair

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

ESTIMATED NORMAL PERIOD FOR REPAIR:

Inspected By

5b.

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

6 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser