

3. REC BY: [Signature]

REF:

CS3/C9/22207092/Tnp31

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / VS / TPRES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop no/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: _____
IDAC Accident Rpt _____ Consistent? : Yes or No
GIA / PR Seen _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLZ 87010 Yr Regnt: 2018 May
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz B180 c.c. 1595
Colour: Grey A/C: Insured / Std / NI / NA
Sp. Reading _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2462472 J4 76345

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: _____ R: _____

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.L. 6/1/23

Survey held at

Chipp Soon Ah

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS \$: _____

Photos _____

Others _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech Insp (\$ _____)

☐ : Weekend (\$ _____)

Report Format: _____

Lump Sum / L.S.K. (\$) _____