



PRIORITY SERVICES (SG) PTE LTD

Insurance Loss Adjusters and Motor Appraisers

Blk 779 Yishun Avenue 2

#01-1545 Singapore 760779

Tel: 6293 4822 Fax: 6296 3283

E-mail: admin@priorityservices.sg

Vehicle Inspection Report

Report No. IN-0003/04/21	Date of Report	: 20/04/2021
To : MCS Logistics (S) Pte Ltd	Date of Request	: 01/03/2021
1 Kaki Bukit Road 2	Report requested by	: MCS Logistics (S) Pte Ltd
#04-06 Eunus Warehouse Complex	Date of Inspection	: 01/03/2021
Singapore 417835	Date of Accident	: 21/01/2021
Policy No :	Sum Insured	-
Claim No : Third Party Claim	Excess (S\$)	: N/A
	Insured Vehicle	

PARTICULARS OF DAMAGED VEHICLE

Registration Plate No	: GBH 6663 G	Odometer Reading	: 94185 km
Make / Model	: Nissan NV200 (M)	Radio / CD	: Yes
Year	: 2018	Air-conditioner	: Yes
Colour	: Met. Grey	Wing Mirror	: Yes
Engine Capacity	: 1461 cc	View Cam	: Yes
Engine No	: -	Seat Belts	: Yes
Chassis / Frame No	: VSKYBAM20Z0170224	Accessories	: -
Carrying Capacity	: 3100 kg		

TYRE CONDITION

Front Left	: 6mm	Front Right	: 6mm
Make	: Grenlander	Make	: Grenlander
Rear Left	: 6mm	Rear Right	: 6mm
Make	: Grenlander	Make	: Grenlander
Spare	:	Road Wheels Type	: Standard

(The above represents the approximate remaining life of tyre treads)

Tools	: Intact	Spare tyre	: Intact
-------	----------	------------	----------

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (static tests only)

General bodywork	: Good
Paintwork	: Good
Handbrake	: Serviceable
Footbrake	: Serviceable
Steering	: Serviceable
Apparent engine modification	: Nil

This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.



PRIORITY SERVICES (SG) PTE LTD

Insurance Loss Adjusters and Motor Appraisers

Blk 779 Yishun Avenue 2

#01-1545 Singapore 760779

Tel: 6293 4822 Fax: 6296 3283

E-mail: admin@priorityservices.sg

ASSESSMENT

		Repairer's Estimate (S\$)	Our Recommendation (S\$)
Spare Parts	:	11,370.20	5,552.80
Labour Charges	:	2,530.00	1,460.00
Paint Work	:	350.00	300.00
Towing Charges	:	0.00	0.00
Others	:		
Totals	:	14,250.20	7,312.80

Reduction (S\$) : 8,400.20

Recommended Reserve (S\$) : 5,850.00 (Lump Sum)

Estimated Normal Period of Repairs : 5 working days

CONTRIBUTIONS BY INSURED

Excess (S\$) : N/A

Others :

GENERAL REMARKS

WITHOUT PREJUDICE

Continuation Sheet

The Assignment

The survey was conducted at M/s. ASM Automotive Services Pte Ltd, No. 13 Pioneer Sector 1, Singapore 628424
Follow-up inspection has been conducted.

Point of Impact

At the front portion.

Damages

The front bumper, front bumper reinforcement, front bumper sponge, intercooler, radiator grille lower garnish, etc.

Other parts were also found damaged. (see schedule for details)

Adjustment / Recommendation

We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle and we list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is \$7,312.80

Conclusion

The repairer has agreed to undertake repairs at a lump sum of \$5,850.00

Pre-accident market value : About \$59,000.00

COE rebate from LTA : \$22,571.00 (COE expiry on 26-08-2028)

We now revert to you for your decision on repairs.

Very truly yours

PRIORITY SERVICES (SG) PTE LTD



LAWRENCE NG, MSAAA
Motor Appraiser

Encl. Photographs of the damaged vehicle taken by us during inspection.

Vehicle No : GBH 6663 G Nissan NV200 (M)
Workshop : ASM Automotive Services Pte Ltd

IN-0003/04/21

Description	Condition	Repairer's Estimate (S\$)	Dist %	Our Recommendation (S\$)	Dist %
To Supply :					
1pc. radiator grille	refit	460.00	10	nn X 0.00	10
1pc. radiator grille lower garnish	cracked	330.00	10	✓ 330.00	10
6pcs. radiator grille clips	necessary	24.00	10	✓ 24.00	10
1pc. radiator core support lower	refit	110.00	10	nn X 0.00	10
1pc. front bumper	dented	560.00	10	✓ 560.00	10
2pcs. bumper fog lamp LH & RH	refit	800.00	10	nn X 0.00	10
2pcs. bumper fog lamp cover LH & RH	complete with front bumper	240.00	10	nn X 0.00	10
1pc. bumper towing cover	dented/defaced	44.00	10	✓ 44.00	10
2pcs. bumper side bracket LH & RH	refit	100.00	10	nn X 0.00	10
1pc. bumper reinforcement	dented	800.00	10	✓ 614.00	10
1pc. bumper energy absorber	cracked	290.00	10	✓ 290.00	10
1pc. bumper lower apron bracket	broken/dislodged/missing	360.00	10	✓ 360.00	10
2pcs. front fender splash shield LH & RH	LH cracked	380.00	10	✓ 190.00	10
1pc. intercooler	dented	2,500.00	10	✓ 2,500.00	10
1pc. radiator assy	refit	1,100.00	10	nn X 0.00	10
1pc. radiator fan assy w/shroud	refit	900.00	10	nn X 0.00	10
1pc. drive shaft RH	refit	2,200.00	10	nn X 0.00	10
1pc. engine lower cover	cracked	370.00	10	✓ 370.00	10
SUPPLEMENTARY:-					
1pc. front air guide cover LH	cracked	130.00	10	✓ 130.00	10
1pc. front air guide cover RH	cracked	130.00	10	✓ 130.00	10
1pc. intercooler hose LH	cracked	700.00	10	✓ 550.00	10
Sub-Total :		12,528.00		6,092.00	
Total Discount :	6092 -10%	1,252.80		609.20	
	5482.80	11,275.20		5,482.80	
Special Nett :					
1pc. front emboss number plate with frame	dented	45.00		35.00	✓
5litres radiator coolant	necessary	50.00		35.00	X nn
Sub-Total :	35	95.00		70.00	
Total Discount :		0.00		0.00	
		95.00		70.00	
Total For Parts :		11,370.20		5,552.80	

Vehicle No : GBH 6663 G Nissan NV200 (M)
Workshop : ASM Automotive Services Pte Ltd

IN-0003/04/21

Labour Charges :					
To remove and replace above damaged parts, realignment etc.		2,450.00		400 ✓ 1,400.00	
To adjust and test drive wheel alignment system.		80.00		60.00 ✓	
Spray Painting Charges :					
Respray on affected areas and panels.		350.00		200 ✓ 300.00	
	660				
Grand Total :		14,250.20		7,312.80	

Surveyor : LAWRENCE NG

6177.80

L/S - 4942.24
= 4950

4 days