



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 6663G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RADIATOR GRILLE	NOT NECESSARY	460.00	-
1	RADIATOR GRILLE LOWER GARNISH	CRACKED	330.00	330.00
6	RADIATOR GRILLE CLIPS	NECESSARY	24.00	24.00
1	RADIATOR CORE SUPPORT LOWER	NOT NECESSARY	110.00	-
1	FRONT BUMPER	DENTED	560.00	560.00
2	BUMPER FOG LAMP LH & RH	NOT NECESSARY	800.00	-
2	BUMPER FOG LAMP COVER LH & RH	NOT NECESSARY	240.00	-
1	BUMPER TOWING COVER	DENTED / DEFACED	44.00	44.00
2	BUMPER SIDE BRACKET LH & RH	NOT NECESSARY	100.00	-
1	BUMPER REINFORCEMENT	DENTED	800.00	614.00
1	BUMPER ENERGY ABSORBER	CRACKED	290.00	290.00
1	BUMPER LOWER APRON BRACKET	BROKEN / DISLODGED / MISSING	360.00	360.00
2	FRONT FENDER SPLASH SHIELD LH & RH	N/S CRACKED	380.00	190.00
1	INTERCOOLER	DENTED	2,500.00	2,500.00
1	RADIATOR ASSY	NOT NECESSARY	1,100.00	-
1	RADIATOR FAN ASSY W/SHROUD	NOT NECESSARY	900.00	-
1	DRIVE SHAFT RH	NOT NECESSARY	2,200.00	-
1	ENGINE LOWER COVER	CRACKED	370.00	370.00
1	FRONT AIR GUIDE COVER LH	CRACKED	130.00	130.00
1	FRONT AIR GUIDE COVER RH	CRACKED	130.00	130.00
1	INTERCOOLER HOSE LH	CRACKED	700.00	550.00
	LESS 10% DISCOUNT		-1,252.80	-609.20
			11,275.20	5,482.80
<u>SPECIAL NETT ITEMS</u>				
1	FRONT EMBOSS NUMBER PLATE WITH FRAME (SN)	DENTED	45.00	35.00
5	LITRES RADIATOR COOLANT (SN)	NOT NECESSARY	50.00	-
			95.00	35.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE ABOVE DAMAGED PARTS, REALIGNMENT ETC.		2,450.00	400.00
	TO ADJUST AND TEST DRIVE WHEEL ALIGNMENT STSTEM.		80.00	60.00
	RESPRAY ON AFFECTED AREAS AND PANELS.		350.00	200.00
			2,880.00	660.00
GRAND TOTAL			14,250.20	6,177.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,950.00

Report Ref No. CS1/MIDA22012957/Dpe2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.