

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988

**Our File No:** CS/EGI22012959/RVY3M4**Date:** 01/03/2023**REFERENCE**

Insured/Claimant:	CHUA SIAK MONG	Policy No:	0
Date of Loss:	23/12/2022	Nature of Claim:	OD Claim No: CDMPG22002784

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLT1719G</b>		
Make & Model:	MERCEDES-BENZ GLA180 URBAN (R18 LED), 1.6 (A)	Engine No:	27091031413113
Reg. Date:	20/10/2017 (Man. Year: 2017)	Chassis No:	WDC1569422J422573
Colour:	Grey	Odometer:	47825 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	S\$108,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,310.93	6,789.72	4,521.21	39.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	1,070.00	460.00	30.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,840.93</b>	<b>7,859.72</b>	<b>4,981.21</b>	<b>38.79</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,300.00</b>		
<b>- Excess (S\$)</b>	0.00	500.00	-500.00	
<b>(S\$)</b>	12,840.93	5,800.00	7,040.93	54.83
<b>+ GST 7.00/7.00% (S\$)</b>	898.87	406.00	492.87	54.83
<b>Nett Amount (S\$)</b>	<b>13,739.80</b>	<b>6,206.00</b>	<b>7,533.80</b>	<b>54.83</b>

**INSPECTION**

Date of Assignment:	29/12/2022	Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	30/12/2022	Inspected At:	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792
Estimated Period of Repair:	4.0 days		

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Mar 2023)
Parts:	M1-SUV	MERCEDES-BENZ GLA180 URBAN (R18 LED) 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT1719G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH (WCP)	Cracked	3,765.00 F	*3,332.00 F
2	1		*FRONT SUPPORT PANEL (WCP)	Serviceable	1,248.00 F	*- F
3	1		*FRONT SUPPORT PANEL BRACKET LH (WCP)	Serviceable	69.30 F	*- F
4	1		*FRONT BUMPER (WCP)	Deformed	2,074.00 F	*1,467.00 F
5	1		*FRONT BUMPER FINISHER COVER LH (WCP)	Missing	113.00 F	*45.81 F
6	1		*FRONT BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
7	1		*FRONT GRILLE ASSY (WCP)	Serviceable	392.00 F	*- F
8	1		*FRONT GRILLE BASE (WCP)	Serviceable	443.00 F	*- F
9	1		*FRONT BUMPER FINISHER BRACKET LH (WCP)	Serviceable	105.00 F	*- F
10	1		*FRONT FENDER LH (WCP)	Bent	1,350.00 F	*885.00 F
11	1		*FRONT FENDER INNER LINER LH (WCP)	Cracked	319.00 F	*181.30 F
12	1		*FRONT FENDER EXTENSION COVER LH (WCP)	Deformed	368.00 F	*225.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	10,286.30	6,176.11
+ Margin on L,N Items 10.00/10.00% (S\$)	1,024.63	613.61
Total Parts (S\$)	11,310.93	6,789.72

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REPLACE & REFIT FRONT RADIATOR, AIR COND CONDENSOR & ETC. TO EFFECT REPLACE OF FRONT SUPPORT PANEL	New	100.00	0.00
2	TO REMOVE & REPLACE & REFIX & READJUST FRONT ACCIDENT AREA SUCH AS FRONT GRILLE, FRONT BUMPER, FRONT FENDER LH, FRONT HEADLAMP & ETC. BACK TO ORIGINAL CONDITION	New	580.00	480.00
3	TO SUUPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER & ETC	New	400.00	400.00
4	TO REFILL AIRCOND GAS & VACUUM	New	100.00	0.00
5	TO REMOVE & REFIX FRONT BUMPER DISTANCE SENSOR, DISTANCE SENSOR RADAR & ETC. TO EFFECT REPLACE OF FRONT BUMPER	New	120.00	60.00
6	TO DIAGNOSIS FAULTY CODE & RESET MEMORY	New	150.00	100.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM	New	80.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>1,530.00</b>	<b>1,070.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >