

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS6/AIS22012960/CNY3E2**Date:** 12/06/2023**REFERENCE**

Insured/Claimant:	THIA TUAN LIANG ADRIAN	Policy No:	SP2001192609-01	
Date of Loss:	11/12/2022	Nature of Claim:	OD	Claim No: 202222008813

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDH681U		
Make & Model:	BMW 640I, 3.0 GRAN COUPE M SPORT LED SR NAV HUD (A)	Engine No:	HIDDEN
Reg. Date:	28/09/2012 (Man. Year: 2012)	Chassis No:	WBA6A02080DZ10764
Colour:	Black	Odometer:	0 km
Engine Capacity:	2979 cc		
Market Value/New Car Price:	S\$138,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/35 R20	Rear Tyre Size:	265/35 R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,004.60	8,069.60	935.00	10.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,330.00	1,030.00	300.00	22.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,334.60	9,099.60	1,235.00	11.95
- Excess (S\$)	0.00	800.00	-800.00	
(S\$)	10,334.60	8,299.60	2,035.00	19.69
+ GST 7.00/8.00% (S\$)	723.42	663.97	59.45	8.22
Nett Amount (S\$)	11,058.02	8,963.57	2,094.45	18.94

INSPECTION

Date of Assignment:	29/12/2022	Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	29/12/2022	Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	3.0 days		

Adjuster: SIMON HO LEONG CHUAN**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jun 2023)
Parts:	143	BMW 640I 3.0 GRAN COUPE M SPORT LED SR NAV HUD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDH681U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER (M SPORTS) (WCP)	Dented	1,800.00 F	*1,600.00 F
2	1		*FRT BUMPER PARKING SENSOR (LH) (WCP)	Missing	180.00 F	*180.00 F
3	1		*FRT BUMPER PARKING SENSOR O RING (LH) (WCP)	Not Necessary	6.00 F	*- F
4	1		*FRT BUMPER HOLDER (LH) (WCP)	Missing	15.00 F	*15.00 F
5	1		*FRT HEADLAMP (LH) (WCP)	Cracked	4,500.00 F	*4,500.00 F
6	1		*FRT HEADLAMP BRACKET (LH) (WCP)	Cracked	55.00 F	*170.00 F
7	1		*FRT HEADLAMP NOZZLE (LH) (WCP)	Not Necessary	190.00 F	*- F
8	1		*FRT HEADLAMP NOZZLE COVER (LH) (WCP)	Bent	60.00 F	*50.00 F
9	1		*FRT HEADLAMP NOZZLE SPRING (LH) (WCP)	Bent	23.00 F	*6.00 F
10	1		*FRT FENDER INNERSHIELD (LH) (WCP)	Not Necessary	100.00 F	*- F
11	1		*FRT FOGLAMP (LH) (WCP)	Not Necessary	230.00 F	*- F
12	1		*FRT FOGLAMP GRILLE (WCP)	Not Necessary	52.00 F	*- F
13	1		*FRT AIR DUCT (LH) (WCP)	Cracked	55.00 F	*45.00 F
14	1		*FRT EMBLEM (WCP)	Necessary	80.00 F	*80.00 F
Supplementary #1						
15	1		*FRT HEADLAMP NOZZLE BRACKET(LH) (WCP)	Distorted	15.00 F	*15.00 F
16	1		*FRT BUMPER SPONGE (WCP)	Cracked	55.00 F	*55.00 F
17	1		*FRT BUMPER REINFORCEMENT (WCP)	Dented	620.00 F	*620.00 F
18	1		*FRT PARKING SENSOR WIRING (WCP)	Repair	150.00 F	*- F

F=Franchise part.

Sub Total (\$\$)	8,186.00	7,336.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	818.60	733.60
Total Parts (\$\$)	9,004.60	8,069.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK, WELD,REMOVE & FIX ABOVE PARTS	New	650.00	500.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREA	New	450.00	350.00
3	TO CHECK WIRING	New	30.00	30.00
4	TO DIAGNOSE & RESET FAULT CODE	New	200.00	150.00
Gross Labour Cost (\$\$)			1,330.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >