

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG22012965/KYA3Q2**Date:** 12/05/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070133808
<b>Claimant Vehicle No :</b>	SHD495P	<b>Insured Vehicle No :</b>	SMV407R
Date of Loss:	21/12/2022	Nature of Claim:	TP
		Claim No:	7567649881SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD495P</b>		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C003260
Reg. Date:	30/11/2017 (Man. Year: 2016)	Chassis No:	VF1ABL15AUC283508
Colour:	Metallic White/Red	Odometer:	539635 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 7 mm	Rear Left Side:	Sailun 7 mm
Front Right Side:	Sailun 7 mm	Rear Right Side:	Sailun 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,498.37	2,291.27	4,207.10	64.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,880.00	890.00	6,990.00	88.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>14,378.37</b>	<b>3,181.27</b>	<b>11,197.10</b>	<b>77.87</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,550.00</b>		
<b>Nett Amount (\$\$)</b>	<b>14,378.37</b>	<b>2,550.00</b>	<b>11,828.37</b>	<b>82.27</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment:	22/12/2022		
Date Inspected:	22/12/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

**Adjuster:** KENNETH KONG**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Bent	747.20 FL	*747.20 FL
2	1		*BUMPER BRACKET KIT FRT RH	Serviceable	101.40 FL	*- FL
3	1		*BUMPER RETAINER FRT RH	Cracked	101.40 FL	*101.40 FL
4	1		*FENDER PANEL FRT RH	Bent	437.10 FL	*437.10 FL
5	1		*WHEELARCH FRT RH	Torn	191.40 FL	*191.40 FL
6	1		*WIPER RESERVOIR	Dented	179.60 FL	*179.60 FL
7	1		*HEADLAMP RH	Cracked	743.60 FL	*743.60 FL
8	1		*DOOR FRT FRT RH	Repair	2,844.66 FL	*- FL
9	1		*DOOR HINGE UPPER FRT RH	Repair	261.28 FL	*- FL
10	1		*DOOR HINGE LOWER FRT RH	Repair	300.55 FL	*- FL
11	1		*FRONT BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
12	1		*RIM	Serviceable	350.00 FS	*- FS
13	1		*TYRE	Serviceable	300.00 FS	*- FS
14	1		*FENDER LINER CLIP	Necessary	65.00 FS	*65.00 FS
15	1		*DOOR STICKER TRANSCAB	Not Necessary	100.00 FS	*- FS
16	1		*DOOR STICKER TEL NO	Not Necessary	100.00 FS	*- FS
17	1		*DOOR ADVERTISEMENT	Not Necessary	200.00 FS	*- FS
					Sub Total (S\$)	7,089.19 2,531.30
					- List Item Discount on L Items 10.00/10.00% (S\$)	590.82 240.03
					Total Parts (S\$)	6,498.37 2,291.27

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	3,000.00	400.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
5	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
6	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
8	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
9	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
11	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
12	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,880.00</b>	<b>890.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >