



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SY 9311L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BENT / TORN / CUT	1,392.00	1,392.00
1	REAR BUMPER LOWER	TORN	382.00	382.00
1	REAR BUMPER LOWER CHROME MOULDING	CUT / BENT	256.00	256.00
2	REAR BUMPER RETAINERS	NOT NECESSARY	161.10	-
2	REAR BUMPER SIDE RETAINERS	NECESSARY	104.00	104.00
1	REAR BUMPER TOW COVER	NOT NECESSARY	62.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	756.00	-
1	REAR BUMPER INNER CORE	NOT NECESSARY	398.00	-
4	REAR BUMPER SENSOR	DAMAGED (2PCS ONLY)	1,036.00	518.00
1	REAR N/S BUMPER INNER LOWER COVER	BENT	105.00	105.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	855.00	-
	LESS 10% DISCOUNT		-550.71	-275.70
			4,956.39	2,481.30
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIPS / FASTENERS (SN)	NECESSARY	50.00	30.00
1	REAR BUMPER SECURE RIVETS (SN)	NECESSARY	60.00	20.00
			110.00	50.00
<u>LABOUR</u>				
	TO DISCONNECT, CHECK ELECTRICAL WIRING, HARNESS WIRES, SOCKETS, REPLACE DAMAGED LAMPS, CONNECTORS, REAR SENSORS, RECONNECT AND TEST FOR PROPER FUNCTIONING.		100.00	60.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, RE-ALIGN AND RESHAPE INCLUDING CUT AND WELD BODY PANELS REPAIRS, RE-POSITION AND RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS, JIGS AND OTHER GAS OR ELECTRICAL EQUIPMENTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINT THE REPLACE AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPERS, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO NECESSARY.		600.00	400.00
			1,500.00	860.00
GRAND TOTAL			6,566.39	3,391.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,700.00

Report Ref No. CS3/LPC22000769/Dny3e2-1

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.