

Navigation icons: back, forward, search, refresh, zoom (100%), print, and search input field with 'Find | Next' text.



**LKK Auto Consultants Pte Ltd**  
 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933  
 TEL: 6256 3561 FAX: 6256 4315  
 Reg. No: 199607198R GST Reg. No. 19-9607198-R

<b>Affiliated to Federation Internationale Des Experts En Automobile</b>				CS3/LPC22000769/Gny3-1
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: <del>CS3/LPC22000769/Gny3-1</del> Date: 21/01/2022 Code: LPC2		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
<b>Insured Veh.</b>	SCY 1581R	<b>Veh. Inspected</b>	SY 9311L	
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00	
<b>Claim No.</b>	22/22/22/N/P05/025389	<b>Excess (\$)</b>	0.00	
<b>Assign From</b>	GERALD POH	<b>Assign Date</b>	<del>21/01/2022</del> 24/12/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
<b>Make &amp; Model</b>		<b>c.c</b>	0	
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>		
<b>Chassis No.</b>		<b>Colour</b>		
<b>Odometer</b>	-	<b>Steering</b>		
<b>Brakes</b>		<b>Modification</b>		
<b>General</b>				
<b>3. Conditions of Tyres</b>				
	<b>Size</b>	<b>Make</b>	<b>Balance</b>	
<b>R/H Front Tyre</b>			mm	
<b>L/H Front Tyre</b>			mm	
<b>R/H Rear Tyre</b>			mm	
<b>L/H Rear Tyre</b>			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
<b>Accident Date</b>	21/01/2022	<b>Inspection Date</b>	24/01/2022	
<b>Survey held at</b>	TECK SIANG MOTOR SERVICE BLK 5034 ANG MO KIO INDUSTRIAL PARK 2 #01-331. SINGAPORE 569537			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				