

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4976S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CRACKED	459.40	459.40
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
2	REAR BUMPER REINFORCEMENT BRKT RH / LH @\$55.80	NOT NECESSARY	111.60	-
1	REAR BUMPER CENTRE MOULDING	DEFORMED	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING	CUT	155.00	155.00
1	REAR BUMPER UNDER CENTRE COVER	NOT NECESSARY	225.00	-
10	REAR BUMPER COVER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER FOGLAMP	NOT NECESSARY	201.50	-
1	REAR SMART KEY ANTENNA	NOT NECESSARY	40.50	-
	LESS 20% DISCOUNT		-412.21	-217.53
			1,648.84	870.12
	NETT ITEMS			
1	REVERSE SENSOR (N)	NOT NECESSARY	180.00	-
1	REAR NO. PLATE WITH TRIM COVER (N)	SCRATCHED	55.00	55.00
	LESS 10% DISCOUNT		-23.50	-5.50
			211.50	49.50
	SPECIAL NETT ITEMS			
2	REAR FENDER ADV.STICKER RH / LH @\$100.00 (SN)	NECESSARY	200.00	200.00
			200.00	200.00
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE / REFIX REVERSE SENSOR.		120.00	40.00
			820.00	640.00
	GRAND TOTAL		2,880.34	1,759.62





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,400.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. NS/INC22012970/Rqp3e2

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

T

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**