

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22012971/KYA3Q2**Date:** 12/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1210001244
Claimant Vehicle No :	SHD528D	Insured Vehicle No :	SLD8292H
Date of Loss:	15/12/2022	Nature of Claim:	TP
		Claim No:	3506181570SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD528D		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C003192
Reg. Date:	17/11/2017 (Man. Year: 2016)	Chassis No:	VF1ABL15AUC283512
Colour:	Metallic White/Red	Odometer:	370441 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Grenlander 9 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Grenlander 9 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,032.53	1,892.37	1,140.16	37.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,880.00	890.00	6,990.00	88.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,912.53	2,782.37	8,130.16	74.50
Approved Total (Overridden) (\$\$)		2,250.00		
Nett Amount (\$\$)	10,912.53	2,250.00	8,662.53	79.38
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	27/12/2022	
Date Inspected:	27/12/2022	Inspected At: Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled	747.20 FL	*747.20 FL
2	1		*BUMPER BRACKET KIT FRT RH	Serviceable	101.40 FL	*- FL
3	1		*BUMPER RETAINER FRT RH	Distorted	101.40 FL	*101.40 FL
4	1		*FENDER PANEL FRT RH	Bent	437.10 FL	*437.10 FL
5	1		*WHEELARCH FRT RH	Serviceable	191.40 FL	*- FL
6	1		*WIPER RESERVOIR	Serviceable	179.60 FL	*- FL
7	1		*HEADLAMP RH	Mtg Cracked	743.60 FL	*743.60 FL
8	1		*FRONT BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
9	1		*RIM	Serviceable	350.00 FS	*- FS
10	1		*TYRE	Serviceable	300.00 FS	*- FS
11	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
					<hr/>	
					Sub Total (S\$)	3,282.702,095.30
					- List Item Discount on L Items 10.00/10.00% (S\$)	250.17202.93
					<hr/>	
					Total Parts (S\$)	3,032.531,892.37
					<hr/>	

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
3	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	3,000.00	400.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
5	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
6	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
8	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
9	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
11	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
12	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
Gross Labour Cost (\$\$)			7,880.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >