



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7253E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRT FENDER LH	BUCKLED	663.00	663.00
1	FENDER RETAINER LH	NECESSARY	24.60	24.60
1	HEADLAMP LH	SCRATCHED	1,388.00	1,388.00
1	FRONT BUMPER COVER	SCRATCHED	1,052.20	1,052.20
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT BUMPER SIDE BRACKET LH	NOT NECESSARY	24.60	-
1	FRT WHEEL HUB CAP LH	SCRATCHED	217.20	217.20
	LESS 20% DISCOUNT		-678.32	-673.40
			2,713.28	2,693.60
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRT TYRE LH (SN)	NOT NECESSARY	216.00	-
1	FRT DOOR COMFORT LOGO LH (SN)	NOT NECESSARY	75.00	-
			291.00	-
<b><u>LABOUR</u></b>				
	PANEL BEATING.		600.00	560.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	TUFF KOTE.		60.00	40.00
	CHECK ALL LIGHTING.		60.00	30.00
			1,320.00	1,130.00
<b>GRAND TOTAL</b>			<b>4,324.28</b>	<b>3,823.60</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>3,050.00</b>

Report Ref No. NS/INC22012972/Rwp3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.