

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBT 2275G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT WIND SHIELD	NOT NECESSARY	322.00	-
1	SIDE MIRROR L/R-SET	CUT	182.00	182.00
1	FRONT HANDLE BAR	NOT NECESSARY	362.00	-
1	FRONT HANDLE BALANCER L/R-SET	BENT	96.00	96.00
2	FRONT HANDLE BAR GRIP L/R-SET	NOT NECESSARY	82.00	-
1	FRONT CLUTCH LEVER LH	NOT NECESSARY	135.00	-
1	FRONT FORK ASSY-SET	NOT NECESSARY	1,525.00	-
1	STEERING CONE BEARING-SET	NOT NECESSARY	92.00	-
1	FRONT WHEEL -SET	NOT NECESSARY	485.00	-
1	FRONT WHEEL BEARING-SET	NOT NECESSARY	85.00	-
1	FRONT LH FOOTREST	BENT	115.00	115.00
1	FRONT LH FOOT GEAR LEVER	BENT	225.00	225.00
1	REAR LH FOOTREST	NOT NECESSARY	115.00	-
	LESS 5% DISCOUNT		-191.05	-
	LESS 10% DISCOUNT		-	-61.80
			3,629.95	556.20
	SPECIAL NETT ITEMS			
1	FRONT HANDLE LEVER PROTECYOR L/R-SET (SN)	CRACKED	275.00	275.00
1	REAR STORAGE BOX (SN)	CUT	280.00	280.00
1	REAR STORAGE BOX BRACKET (SN)	BENT	120.00	120.00
			675.00	675.00
	<u>LABOUR</u>			
	FORK ALIGNMENT.	NOT NECESSARY	120.00	-
	FRONT & REAR WHEEL ALIGNMENT.	NOT NECESSARY	140.00	-
	TO REPAIR,ALIGN AND BALANCE BODY MAIN FRAME.	NOT NECESSARY	250.00	-
	LABOUR FOR REPAIR AND REPLACE PARTS.		800.00	250.00
			1,310.00	250.00
	GRAND TOTAL		5,614.95	1,481.20

Report Ref No. CS3/LPC22008207/Rqy3e2-1



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,150.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS3/LPC22008207/Rqy3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

P

ANG BRYAN TANI

Automotive Assessor / Investigator