2/6/23, 2:18 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22012975/RQP3E2

M16A2014413

133887 km

TSMJYB22S00411795

**Date:** 06/02/2023

**REFERENCE** 

Handling Insurer: China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No: DMPCSNW00146822204

**Claimant Vehicle** 

SMN8976D

Insured Vehicle No :

SJG8176T

**Engine No:** 

Odometer:

Date of Loss:

Reg. Date:

No:

27/12/2022

Nature of Claim: TP

Claim No:

SNM22D209344/C02/KHONGLH

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMN8976D

Make & Model: SUZUKI S-CROSS, 1.6 (A)

23/05/2017 (Man. Year: 2016) Chassis No:

Colour: Brown

Engine Capacity: 1586 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17
Front Left Side: Giti 6 mm Rear Left Side: Giti 6 mm
Front Right Side: Giti 6 mm Rear Right Side: Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		60,152.00	51,931.00	8,221.00	13.67
Miscellaneous Items		0.00	0.00	0.00	
Labour		28,832.00	12,832.00	16,000.00	55.49
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	88.984.00	64.763.00	24.221.00	27.22

**INSPECTION** 

Date of Assignment: 29/12/2022

Date Inspected: 03/01/2023 Inspected At: 24 Benoi Sector

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(EXCLUDE CHECK ITEMS S\$10,890.00 NETT)

MARKET VALUE: \$66,000.00 (est)

LTA REBATE : \$36,859.00 NETT VALUE : \$29,141.00 Adjuster Report

## **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Feb 2023)

Parts: M1-SUV SUZUKI S-CROSS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMN8976D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,050.00 FS	*1,050.00 FS
2	1		*FRONT BUMPER SIDE RETAINER - LH / RH	N/S Cracked/O/S Not Necessary	72.00 FS	*36.00 FS
3	1		*FRONT BUMPER WIRE HARNESS (NPA)	* Check	0.00 FS	*-FS
4	1		*RADIATOR GRILLE	Cracked	735.00 FS	*735.00 FS
5	1		*FRONT BUMPER - LOWER	Cracked	960.00 FS	*960.00 FS
6	1		*FRONT BUMPER TRIM - LOWER	Scratched	390.00 FS	*390.00 FS
7	1		*FOG LAMP COVER - LH / RH	N/S Cracked/O/S Not Necessary	420.00 FS	*210.00 FS
8	2		*HEADLIGHT - LH / RH	Cracked	15,300.00 FS	15,300.00 FS
9	1		*FRONT WHEEL ARCH TRIM - LH / RH	N/S Deformed/O/S Not Necessary	540.00 FS	*270.00 FS
10	1		*FOAM	Cracked	360.00 FS	*360.00 FS
11	2		*FRONT WHEEL HOUSING GARNISH - LH / RH	N/S * Check / O/S NotNecessary	420.00 FS	*- FS
12	1		*BONNET	Buckled	3,714.00 FS	*3,714.00 FS
13	2		*BONNET HINGE - LH / RH	Bent	150.00 FS	*150.00 FS
14	1		*FRONT FENDER - LH / RH	N/S Bent / O/S Not Necessary	1,320.00 FS	*660.00 FS
15	2		*RADIATOR AIR GUIDE - LH / RH	* Check	96.00 FS	*- FS
16	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	990.00 FS	*990.00 FS
17	1		*FRONT BUMPER SUPPORT	* Check	630.00 FS	*- FS
18	1		*FRONT WINDSCREEN	Cracked	2,775.00 FS	*2,775.00 FS
19	1		*FRONT STEERING AIR BAG	Activated	2,691.00 FS	*2,691.00 FS
20	1		*FRONT DRIVER KNEE AIRBAG	Activated	2,415.00 FS	*2,415.00 FS
21	1		*FRONT DRIVER KNEE AIRBAG COVER	Deformed	195.00 FS	*195.00 FS
22	1		*FRONT PASSENGER AIR BAG	Activated	1,500.00 FS	*1,500.00 FS
23	1		*FRONT PASSENGER AIR BAG COVER	Cracked	570.00 FS	*570.00 FS
24	2		*FRONT SEAT BELT - LH / RH	Activated	3,840.00 FS	*3,840.00 FS
25	2		*FRONT SEAT BELT ADJUSTER - LH / RH (NPA)	* Check	0.00 FS	*- FS
26	1		*FRONT AIR BAG CONTROL UNIT	Activated	1,860.00 FS	*1,860.00 FS
27	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
28	1		*FRONT WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
29	1		*REAR LID	Bent	2,160.00 FS	*2,160.00 FS
30	2		*REAR LID HINGE - LH / RH	* Check	120.00 FS	*- FS
31	1		*REAR LID INNER TRIM	* Check	540.00 FS	*- FS
32	1		*REAR LID GARNISH	* Check	450.00 FS	*-FS
33	1		*REAR LID WEATHER STRIP	Necessary	270.00 FS	*270.00 FS
34	1		*REAR LID EMBLEM SUZUKI	Necessary	60.00 FS	*60.00 FS
35	1		*REAR LID EMBLEM SX4	Necessary	75.00 FS	*75.00 FS
36	1		*REAR LID EMBLEM S-CROSS	Necessary	90.00 FS	*90.00 FS
37	1		*REAR LID EMBLEM ALL GRIP	Necessary	90.00 FS	*90.00 FS
38	1		*REAR BUMPER	Torn	1,200.00 FS	*1,200.00 FS
39	1		*REAR BUMPER SIDE RETAINER - LH / RH	N/S Necessary/O/SNotNecessary	90.00 FS	*45.00 FS
			Report was unsubmitted of			

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR BUMPER REINFORCEMENT - LH / RH (2PCS)	Bent (1Pc Only)	510.00 FS	*255.00 FS
41	1		*REAR BUMPER - LOWER	Deformed	960.00 FS	*960.00 FS
42	2		*REAR BUMPER LOWER SUPPORT - LH / RH	* Check	210.00 FS	*-FS
43	1		*REAR BUMPER LOWER TRIM	Deformed	480.00 FS	*480.00 FS
44	1		*REAR BUMPER LOWER FOG LAMP COVER	Missing	30.00 FS	*30.00 FS
45	1		*REAR BUMPER REFLECTOR - LH / RH	N/S Cracked / O/S * Check	108.00 FS	*54.00 FS
46	1		*REAR END PANEL	Bent	930.00 FS	*930.00 FS
47	1		*REAR SPARE WHEEL HOUSING PANEL	Buckled	690.00 FS	*690.00 FS
48	1		*REAR SPARE WHEEL HOUSING EXTENSION - LH /	N/S Bent / O/S Not Necessary	360.00 FS	*180.00 FS
49	1		*REAR WINDSCREEN	Not Necessary	1,830.00 FS	*- FS
50	1		*REAR WINDSCREEN MOULDING (NPA)	Necessary	0.00 FS	*-FS
51	1		*REAR BUMPER WIRE HARNESS	* Check	0.00 FS	*-FS
52	4		*REAR BUMPER PARKING AID SENSOR (NPA)	Not Working	0.00 FS	*-FS
53	1		*REAR EXHAUST	Bent	1,890.00 FS	*1,890.00 FS
54	2		*REAR EXHAUST MOUNTING - LH / RH	Necessary	96.00 FS	*96.00 FS
55	1		*REAR EXHAUST HEAT SHIELD	Bent	90.00 FS	*90.00 FS
56	1		*REAR WHEEL HOUSING GARNISH - LH / RH	N/S Cracked/O/S NotNecessary	630.00 FS	*315.00 FS
57	2		*REAR UNDER BODY TRIM - LH / RH	* Check	1,200.00 FS	*-FS
58	1		*REAR NO PLATE	Missing	60.00 FS	*60.00 FS
59	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
60	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
61	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
62	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
63	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
64	1		*SUNDRIES	* Check	700.00 FS	*-FS

Report was unsubmitted during this print-out.

**Total Parts (S\$) 60,152.00** 

51,931.00

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

	rarticulars	Lab.Type	Repairer's	Amount
abour	r Items			
H H	O REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR IEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND IEADLIGHT WASHER ASSY	New	280.00	280.00
Р	O REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND OWER MODULE FRONT)	New	400.00	0.00
A P	O REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS FRONT)(* Check)	R New	1,600.00	0.00
R O	O REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER DLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT		2,800.00	2,800.00
R R	O REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR	New	280.00	0.00
	O RENEW FRONT WINDSCREEN FRONT)	New	480.00	480.00
	O INSTALL SOLAR FILM FOR FRONT WINDSCREEN FRONT)	New	400.00	400.00
	O CARRY OUT WATER SEEPAGE TEST FOR AFFECTED WINDSCREEN FRONT)	New	200.00	0.00
B A C	O DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, CONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,200.00	900.00
10 <b>T</b> (	O RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, IINGES AND LHS FRONT DOOR FRONT)	New	3,000.00	960.00
	O REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION REAR)	New	280.00	280.00
W	O REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM, VIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY REAR)	New	480.00	480.00
	O REMOVE AND REFIT REAR WINDSCREEN	New	480.00	480.00
14 T	O REMOVE AND REINSTALL EXHAUST SYSTEM AND REAR SUSPENSION ASSEMBLY. RENEW ACCORDINGLY	New	2,800.00	0.00
5 <b>T</b>	O REMOVE AND REINSTALL FUEL TANK ASSY REAR)(* Check)	New	600.00	0.00
	O SETUP VEHICLE ON CELLETE BENCH FOR REPAIR REAR)	New	1,800.00	1,800.00
O T M	O DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING AND SPARE WHEEL HOUSING. O REPAIR BOTH REAR FENDERS. RE-ORGANIZE CRASH IANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED REAR)	New	4,400.00	1,800.00
18 <b>T</b>	O RESPRAY REAR BUMPER, REAR LID, BOTH REAR FENDERS, SPARE WHEEL HOUSING AND REAR END PANELLING	New	3,000.00	1,500.00

No	Particulars	Lab.Type	Repairer's	Amount
19	TO CARRY OUT STONE CHIP PRIMER WORK ON REAR PANELLING AND SPARE WHEEL HOUSING (REAR)	New	480.00	480.00
20	TO TOW BACK THE VEHICLE FROM ACCIDENT ACENE (REAR)(* Check)	New	280.00	0.00
21	TO CARRY OUT DIAGNOSTIC CHECK (REAR)	New	192.00	192.00
22	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY (REAR)(* Check)	New	1,400.00	0.00
	Gross Labou	r Cost (S\$)	28,832.00	12,832.00
	Report was unsubmitted during this pri	int-out.		

< END OF ESTIMATES >