

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22012977/KYA3Q2**Date:** 14/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100440034-07
Claimant Vehicle No :	SMZ4023S	Insured Vehicle No :	SKX1444P
Date of Loss:	23/12/2022	Nature of Claim:	TP
		Claim No:	5357019050SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ4023S	Engine No:	L15B6020192
Make & Model:	HONDA SHUTTLE, 1.5 G CVT SENSING (A)	Chassis No:	GK82100149
Reg. Date:	26/04/2021 (Man. Year: 2019)	Odometer:	148899 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/50 R15	Rear Tyre Size:	185/50 R15
Front Left Side:	Arivo 3 mm	Rear Left Side:	Firenza 4 mm
Front Right Side:	Arivo 3 mm	Rear Right Side:	Firenza 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,333.44	9,460.89	9,872.55	51.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,350.00	2,120.00	2,230.00	51.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,683.44	11,580.89	12,102.55	51.10
Approved Total (Overridden) (S\$)		9,250.00		
(S\$)	23,683.44	9,250.00	14,433.44	60.94
+ GST 8.00/8.00% (S\$)	1,894.68	740.00	1,154.68	60.94
Nett Amount (S\$)	25,578.12	9,990.00	15,588.12	60.94
+ Car Rental (10.0 x S\$62.00/day) (S\$)		620.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		10,636.75		

INSPECTION

Date of Assignment:	27/12/2022	
Date Inspected:	27/12/2022	Inspected At: Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	8.0 days	

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,193.70 FL	*1,193.70 FL
2	1		*REAR TAILGATE H LOGO	Necessary	58.00 FL	*58.00 FL
3	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	55.00 FL	*55.00 FL
4	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	75.00 FL	*75.00 FL
5	1		*REAR TAILGATE OUTER GARNISH	Serviceable	483.30 FL	*- FL
6	1		*REAR TAILGATE REFECTOR	N/S Mtg Dented/O/S Serviceable	771.70 FL	*385.85 FL
7	2		*REAR TAILGATE HINGE	Repair	130.00 FL	*- FL
8	2		*REAR TAILGATE ABSORBER	Serviceable	371.00 FL	*- FL
9	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*149.30 FL
10	1		*REAR TAILGATE INNER LOCK	Dented	289.40 FL	*228.40 FL
11	1		*REAR TAILGATE INNER RUBBER (50%)	Distorted / Dented	150.80 FS	*94.25 FS
12	1		*REAR TAILGATE INNER GARNISH	Mtg Cracked	358.50 FL	*280.40 FL
13	1		*REAR TAILGATE INNER HANDLE	Serviceable	68.50 FL	*- FL
14	1		*REAR TAILLAMP	N/S Cracked / O/S Serviceable	1,040.40 FL	*520.50 FL
15	2		*REAR TAILLAMP LOWER BRACKET	Serviceable	179.00 FL	*- FL
16	1		*REAR BUMPER	Bent	1,150.60 FL	*1,150.60 FL
17	1		*REAR BUMPER CHROME	Cracked	285.20 FL	*148.50 FL
18	1		*REAR BUMPER SIDE RETAINER	N/S Distorted	77.00 FL	*38.50 FL
19	2		*REAR BUMPER REFECTOR	Serviceable	130.00 FL	*- FL
20	2		*REAR BUMPER REFECTOR GARNISH	No such part	170.00 FL	*- FL
21	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
22	1		*REAR END PANEL	Bent	601.50 FL	*601.50 FL
23	1		*REAR END PANEL OUTER SENSOR	Serviceable	190.50 FL	*- FL
24	1		*REAR END PANEL INNER SENSOR	Serviceable	185.00 FL	*- FL
25	1		*REAR END PANEL INNER GARNISH	Cracked	295.20 FL	*185.00 FL
26	1		*REAR END PANEL INNER GARNISH COVER	Mtg Cracked	158.50 FL	*158.50 FL
27	1		*REAR END PANEL SIDE PANEL	O/S Repair / N/S Bent	771.00 FL	*285.00 FL
28	2		*REAR END PANEL SIDE GARNISH	Serviceable	317.00 FL	*- FL
29	1		*REAR FLOOR PANEL	Repair	985.50 FL	*- FL
30	1		*REAR FLOOR PANEL GARNISH BOX	Cracked	495.80 FL	*488.20 FL
31	1		*REAR FLOOR PANEL TOP CARDBOARD	Serviceable	685.00 FL	*- FL
32	1		*REAR FENDER INNER GARNISH (O/S SERVICEABLE)	N/S Buckled/Distorted	1,517.60 FL	*485.00 FL
33	1		*FRONT CENTRE GRILLE BASE	Cracked	495.00 FL	*385.10 FL
34	1		*FRONT CENTRE GRILLE OUTER GARNISH	Dented	325.50 FL	*325.50 FL
35	1		*FRONT CENTRE GRILLE H LOGO	Scratched	58.50 FL	*58.50 FL
36	1		*FRONT CENTRE GRILLE TOP GARNISH	Serviceable	195.00 FL	*- FL
37	8		*FRONT CENTRE GRILLE TOP GARNISH CLIP	Not Necessary	40.00 FL	*- FL
38	1		*FRONT CENTRE GRILLE LOWER CHROME	Dented	215.00 FL	*215.00 FL
39	1		*FRONT HEADLAMP	N/S Cracked / O/S Serviceable	5,100.00 FL	*2,250.00 FL
40	2		*FRONT HEADLAMP CHROME	Serviceable	311.00 FL	*- FL
41	1		*FRONT HEADLAMP LOWER BRACKET	N/S Cracked	116.00 FL	*58.00 FL
42	1		*FRONT BUMPER	Buckled	1,150.50 FL	*1,050.00 FL
43	20		*FRONT BUMPER CLIP	Necessary	100.00 FL	*100.00 FL
44	1		*FRONT BUMPER SIDE RETAINER	N/S Distorted	70.00 FL	*35.00 FL
45	1		*FRONT BUMPER REINFORCEMENT	Bent	420.90 FL	*338.00 FL
46	1		*FRONT BUMPER LOWER GRILLE	Serviceable	158.60 FL	*- FL
47	2		*FRONT BUMPER FOG LAMP GARNISH	Serviceable	371.00 FL	*- FL
48	2		*FRONT BUMPER FOG LAMP GARNISH TOP COVER	Serviceable	157.00 FL	*- FL
49	1		*FRONT SUPPORT PANEL	Repair	760.40 FL	*- FL
50	1		*SET REAR PARKING SENSOR	Shorted	280.00 FS	*200.00 FS
51	1		*SET REAR & FRONT NUMBER PLATE & CASING	Front Dented	100.00 FS	*45.00 FS
52	1		*SEALANT	Necessary	100.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	24,009.10
					11,731.30	
					- List Item Discount on L Items 20.00/20.00% (\$)	4,675.66
						2,270.41
					Total Parts (\$)	19,333.44
						9,460.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
2	WIRING	New	80.00	40.00
3	TUFFKOTE	New	150.00	60.00
4	SPRAY PAINTING	New	2,000.00	900.00
5	LABOUR CHARGES	New	2,000.00	1,000.00
Gross Labour Cost (S\$)			4,350.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >