

ASS. REC. BY:

REF: A/GKennerth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 7-8 days

Res.: Yes or No

Lump Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: Sm 7 40235Yr Regn: 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: HondaWagonColour: M. Black

A/C: Insured / Std / NI / NA

Sp. Reading: 148899

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

GK8 2700149Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Mod: MT / S/Rim / STD A/Rim or _____Tyre Size: F Arivo 185/50R15R: Fix 189

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front

Rear

R/Bal. 3 mmR/Bal. 4 mmL/Bal. 3 mmL/Bal. 4 mmD.O.A. 23/12/22D.O.I. 27/12/2022

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or Rear N/S & Fnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 GIA not ready, Get BZ

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee: _____

Transportation: _____

S - RS. SI

: F. P. S.

: O. P. S.

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

23/12/2022

Owner: GRAVITY CAR LEASING PTE LTD

ESTIMATE TO REPAIR HONDA SHUTTLE - SMZ4023S

1pc	rear tailgate			By \$	1,193.70	✓
1pc	rear tailgate "H" logo			in \$	58.00	✓
1pc	rear tailgate "SHUTTLE" emblem			in \$	55.00	✓
1pc	rear tailgate "HYBRID" emblem			in \$	75.00	✓
1pc	rear tailgate outer garnish			in \$	483.30	X
2pcs	rear tailgate reflector @\$385.85	n/s?	o/s in x	\$	771.70	
2pcs	rear tailgate hinge @\$65.00			in \$	130.00	X
2pcs	rear tailgate absorber @\$185.50			in \$	371.00	X
1pc	rear tailgate windscreen moulding			in \$	195.00	✓
1pc	rear tailgate inner lock			\$	289.40	?
1pc	rear tailgate inner rubber			Dist in \$	188.50	50 in
1pc	rear tailgate inner garnish			\$	358.50	?
1pc	rear tailgate inner handle			\$ in	68.50	X
2pcs	rear taillamp @\$520.50	n/s & CM	o/s in x	\$	1,040.40	✓
2pcs	rear taillamp lower bracket @\$89.50			in \$	179.00	X
1pc	rear bumper			By \$	1,150.60	✓
1pc	rear bumper chrome			CM \$	285.20	✓
2pcs	rear bumper side retainer @\$38.50		n/s o/s	\$	77.00	✓
2pcs	rear bumper reflector @\$65.00			\$	130.00	?
2pcs	rear bumper reflector garnish @\$85.00			n/s \$	170.00	X
10pcs	rear bumper clip @\$5.00			in \$	50.00	✓
1pc	rear end panel			By \$	601.50	✓
1pc	rear end panel outer sensor			\$	190.50	?
1pc	rear end panel inner sensor			\$	185.00	?
1pc	rear end panel inner garnish			CM \$	295.20	✓
1pc	rear end panel inner garnish cover			\$	158.50	?
2pcs	rear end panel side panel @\$385.50	o/s in	n/s?	\$	771.00	
2pcs	rear end panel side ganish @\$158.50			\$	317.00	?
1pc	rear float panel			in \$	985.50	X
1pc	rear float panel garnish box			CM \$	495.80	✓
1pc	rear float panel top cardboard			in \$	685.00	X
2pcs	rear fender inner garnish @\$758.80		n/s?	\$	1,517.60	
1pc	front centre grille base			\$	495.00	?
1pc	front centre grille outer garnish			Det \$	325.50	✓
1pc	front centre grille "H" logo			\$	58.50	?
1pc	front centre grille top garnish			in \$	195.00	X

balance c/f

\$ 14,596.40



*Not with car
1/10/23
Running After Paint
7-8 days*

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

23/12/2022

Owner: GRAVITY CAR LEASING PTE LTD

ESTIMATE TO REPAIR HONDA SHUTTLE - SMZ4023S

	balance b/f		\$ 14,596.40
8pcs	front centre grille top garnish clip @\$5.00	na	\$ 40.00 X
1pc	front centre grille lower chrome		\$ 215.00 7
2pcs	front headlamp @\$2550.00	N/S ?	\$ 5,100.00
2pcs	front headlamp chrome @\$155.50	N/S ?	\$ 311.00 X
2pcs	front headlamp lower bracket @\$58.00		\$ 116.00 7
1pc	front bumper	Br	\$ 1,150.50 —
20pcs	front bumper clip @\$5.00	na	\$ 100.00 —
2pcs	front bumper side retainer @\$35.00	N/S DIT	\$ 70.00 4X
1pc	front bumper reinforment		\$ 420.90 7
1pc	front bumper lower grille	Sm	\$ 158.60 X
2pcs	front bumper fog lamp garnish @\$185.50	N/S ?	\$ 371.00
2pcs	front bumper fog lamp garnish top cover @\$78.50	Sm	\$ 157.00 X
1pc	front support panel	R	\$ 760.40 X
			\$ 23,566.80
	less 20%		\$ 4,713.36
	balance c/f		
			\$ 18,853.44

1set	rear parking sensor	Phat	s.nett	\$ 280.00	2000
1set	rear & front number plate & casing	FM Dm	s.nett	\$ 100.00	4500
	remove & refit rear windscreen glass			\$ 120.00	✓
	sealant			\$ 100.00	4000
	wiring			\$ 80.00	400
	tuffkote			\$ 150.00	800
	spray painting			\$ 2,000.00	9000
	labour charges			\$ 2,000.00	10000
	Total				
				\$ 23,683.44	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: