

ASS. REC. BY:

REF:

A/G / 220129771kp

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SM 7 40235

Yr Regn:

04, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

A

Wagon

Colour

M. Blade

A/C:

Insured / Std / NI / NA

Sp. Reading

148899

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GK8

2100149

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Arivo

185/50R15

R: Firm 89

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

4

mm

L/Bal.

3

mm

L/Bal.

4

mm

D.O.A.

23/12/22

D.O.I.

27/12/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S & Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

GIA not ready, Got BZ

3/1

Lump 892501 Cash

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

23/12/2022


Owner: GRAVITY CAR LEASING PTE LTD

ESTIMATE TO REPAIR HONDA SHUTTLE - SMZ4023S

1pc	rear tailgate		Pr	\$	1,193.70	✓
1pc	rear tailgate "H" logo		Pr	\$	58.00	✓
1pc	rear tailgate "SHUTTLE" emblem		Pr	\$	55.00	✓
1pc	rear tailgate "HYBRID" emblem		Pr	\$	75.00	✓
1pc	rear tailgate outer garnish		Pr	\$	483.30	X
2pcs	rear tailgate reflector @\$385.85	n/s mg nd	o/s sw	\$	771.70	✓
2pcs	rear tailgate hinge @\$65.00		Pr	\$	130.00	X
2pcs	rear tailgate absorber @\$185.50		Pr	\$	371.00	X
1pc	rear tailgate windscreen moulding	149.30	Pr	\$	195.00	✓
1pc	rear tailgate inner lock	228.40	nd	\$	289.40	✓
1pc	rear tailgate inner rubber		Dis Mod	\$	188.50	50% 94.25sw
1pc	rear tailgate inner garnish	280.40	mg cm	\$	358.50	✓
1pc	rear tailgate inner handle		Pr	\$	68.50	X
2pcs	rear taillamp @\$520.50	n/s cm	o/s sw	\$	1,040.40	✓
2pcs	rear taillamp lower bracket @\$89.50		Pr	\$	179.00	X
1pc	rear bumper	1150.60	Pr	\$	1,150.60	✓
1pc	rear bumper chrome	148.50	cm	\$	285.20	✓
2pcs	rear bumper side retainer @\$38.50		n/s Dis	\$	77.00	✓
2pcs	rear bumper reflector @\$65.00		Pr	\$	130.00	X
2pcs	rear bumper reflector garnish @\$85.00		n/s Pr	\$	170.00	X
10pcs	rear bumper clip @\$5.00		Pr	\$	50.00	✓
1pc	rear end panel		Pr	\$	601.50	✓
1pc	rear end panel outer sensor		Pr	\$	190.50	X
1pc	rear end panel inner sensor		Pr	\$	185.00	X
1pc	rear end panel inner garnish	185	cm	\$	295.20	✓
1pc	rear end panel inner garnish cover		mg cm	\$	158.50	✓
2pcs	rear end panel side panel @\$385.50	o/s Pr	n/s Pr	\$	771.00	✓ e 285.00
2pcs	rear end panel side ganish @\$158.50		Pr	\$	317.00	X
1pc	rear float panel		Pr	\$	985.50	X
1pc	rear float panel garnish box	488.20	cm	\$	495.80	✓
1pc	rear float panel top cardboard		Pr	\$	685.00	X
2pcs	rear fender inner garnish @\$758.80	o/s sw	n/s Bu Pr	\$	1,517.60	✓ e 485.00
1pc	front centre grille base	385.10	cm	\$	495.00	✓
1pc	front centre grille outer garnish		nd	\$	325.50	✓
1pc	front centre grille "H" logo		Sw	\$	58.50	✓
1pc	front centre grille top garnish		Pr	\$	195.00	X

balance c/f

\$ 14,596.40



NOT Authorized
L1 Prng @ 9250h
Prngng After Prng
-Sday

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

23/12/2022

Owner: GRAVITY CAR LEASING PTE LTD

ESTIMATE TO REPAIR HONDA SHUTTLE - SMZ4023S

balance b/f			\$ 14,596.40
8pcs	front centre grille top garnish clip @\$5.00	na	\$ 40.00 X
1pc	front centre grille lower chrome	nd	\$ 215.00 ✓
2pcs	front headlamp @\$2550.00	n/s part o/s in x	\$ 5,100.00 ✓ + 00250.00
2pcs	front headlamp chrome @\$155.50	n/s in x	\$ 311.00 X
2pcs	front headlamp lower bracket @\$58.00	n/s part	\$ 116.00 ✓
1pc	front bumper 1050	Bu	\$ 1,150.50 —
20pcs	front bumper clip @\$5.00	na	\$ 100.00 —
2pcs	front bumper side retainer @\$35.00	n/s o/s	\$ 70.00 ✓
1pc	front bumper reinforcement 338	Bu	\$ 420.90 ✓
1pc	front bumper lower grille	in	\$ 158.60 X
2pcs	front bumper fog lamp garnish @\$185.50	in	\$ 371.00 X
2pcs	front bumper fog lamp garnish top cover @\$78.50	in	\$ 157.00 X
1pc	front support panel	n	\$ 760.40 X
			\$ 23,566.80
less 20%			\$ 4,713.36
balance c/f			
			\$ 18,853.44

1set	rear parking sensor	photo	s.nett	\$ 280.00	2000n
1set	rear & front number plate & casing	from Del	s.nett	\$ 100.00	45n
	remove & refit rear windscreen glass			\$ 120.00	✓
	sealant			\$ 100.00	405n
	wiring			\$ 80.00	40l
	tuffkote			\$ 150.00	80l
	spray painting			\$ 2,000.00	900n
	labour charges			\$ 2,000.00	1000l
	Total				
				\$ 23,683.44	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____