

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897**Our File No:** CS/AIS22012980/KQY3E2**Date:** 15/03/2023**REFERENCE**

Insured/Claimant:	WEIXIANG HENRY ANG	Policy No:	SP2003362215-01	
Date of Loss:	23/12/2022	Nature of Claim:	OD	Claim No: 202222009116/JK

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SML6475G</b>		
Make & Model:	HONDA FREED HYBRID, 1.5 (A)	Engine No:	LEB5625468
Reg. Date:	29/05/2019 (Man. Year: 2018)	Chassis No:	GB71087435
Colour:	Metallic Blue	Odometer:	53789 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$104,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,514.80	7,909.00	3,605.80	31.31
Miscellaneous Items	60.00	0.00	60.00	100.00
Labour	4,380.00	1,970.00	2,410.00	55.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,954.80</b>	<b>9,879.00</b>	<b>6,075.80</b>	<b>38.08</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,900.00</b>		
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	15,354.80	7,300.00	8,054.80	52.46
<b>+ GST 7.00/7.00% (S\$)</b>	1,074.84	511.00	563.84	52.46
<b>Nett Amount (S\$)</b>	<b>16,429.64</b>	<b>7,811.00</b>	<b>8,618.64</b>	<b>52.46</b>

**INSPECTION**

Date of Assignment:	29/12/2022	Present Location:	Elite Automotive Pte Ltd (HQ) Elite Automotive Pte Ltd (HQ) 280 Woodlands Industrial Park E5, #01-17, Harvest@Woodlands Singapore 757322
Date Inspected:	03/01/2023	Inspected At:	
Estimated Period of Repair:	6.0 days		

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2023)
<b>Parts:</b>	M1-MPV	HONDA FREED HYBRID 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SML6475G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*BONNET</b> (WCP)	Bent	580.00 F	*420.00 F
2	2		<b>*BONNET HINGES (LH &amp; RH)</b> (WCP)	Bent	100.00 F	*100.00 F
3	1		<b>*BONNET INSULATION</b> (WCP)	Serviceable	80.00 F	*- F
4	10		<b>*BONNET INSULATION CLIPS</b> (WCP)	Not Necessary	30.00 F	*- F
5	1		<b>*BONNET STAND</b> (WCP)	Repair	35.00 F	*- F
6	1		<b>*BONNET STAND CLIP</b> (WCP)	Not Necessary	5.00 F	*- F
7	1		<b>*BONNET LOCK</b> (WCP)	Distorted	120.00 F	*120.00 F
8	1		<b>*FRONT BUMPER</b> (WCP)	Cracked	700.00 F	*510.00 F
9	2		<b>*FRONT BUMPER RETAINER (LH &amp; RH)</b> (WCP)	Distorted	40.00 F	*40.00 F
10	10		<b>*FRONT BUMPER CLIPS</b> (WCP)	Necessary	30.00 F	*30.00 F
11	1		<b>*FRONT BUMPER REINFORCEMENT</b> (WCP)	Bent	380.00 F	*260.00 F
12	1		<b>*FRONT BUMPER LOWER GRILLE</b> (WCP)	Serviceable	160.00 F	*- F
13	1		<b>*TOWING CAP</b> (WCP)	Serviceable	18.00 F	*- F
14	1		<b>*FRONT GRILLE</b> (WCP)	Cracked	680.00 F	*510.00 F
15	2		<b>*HEADLAMP (LH &amp; RH)</b> (WCP)	Cracked	2,400.00 F	*2,400.00 F
16	2		<b>*HEADLAMP LOWER BRACKET (LH &amp; RH)</b> (WCP)	Cracked	80.00 F	*80.00 F
17	2		<b>*FRONT FENDER (LH &amp; RH)</b> (WCP)	Buckled	800.00 F	*800.00 F
18	1		<b>*AIRCON CONDENSER</b> (WCP)	Bent	850.00 F	*630.00 F
19	1		<b>*RADIATOR</b> (WCP)	Punctured	980.00 F	*740.00 F
20	2		<b>*FAN COWLING</b> (WCP)	Serviceable	240.00 F	*- F
21	2		<b>*FAN MOTOR</b> (WCP)	Serviceable	560.00 F	*- F
22	2		<b>*FAN BLADE</b> (WCP)	Serviceable	160.00 F	*- F
23	1		<b>*A/C SUCTION PIPE</b> (WCP)	Serviceable	220.00 F	*- F
24	1		<b>*A/C DISCHARGE PIPE</b> (WCP)	Serviceable	260.00 F	*- F
25	1		<b>*A/C LIQUID PIPE</b> (WCP)	Serviceable	280.00 F	*- F

Report was unsubmitted during this print-out.

## Supplementary #1

F=Franchise part.

Sub Total (\$)	10,468.00	7,190.00
+ Margin on L,N Items 10.00/10.00% (\$)	1,046.80	719.00
Total Parts (\$)	11,514.80	7,909.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	FRONT NUMBER PLATE WITH HOLDER (SERVICEABLE)	60.00	0.00
<b>Sub Total (\$\$)</b>			<b>60.00</b>	<b>0.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	New	1,800.00	800.00
2	TO SPRAY PAINTING ON: BONNET, FRONT BUMPER, FRONT BOTH FENDER, SUPPORT PANEL, FRONT BOTH A PILLAR	New	1,800.00	1,000.00
3	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.	New	280.00	0.00
4	TO REMOVE & INSTALL A/C CONDENSER & RECEIVER DRYER, TO ENABLE REPAIRS, TO VACUUM & CHARGE UP GAS.	New	150.00	100.00
5	TO CHECK ELECTRICAL WIRINGS & HEADLIGHTS FUNCTION, INCLUSIVE FOCUS HEADLIGHTS.	New	200.00	20.00
6	TO REMOVE & INSTALL RADIATOR & HOSES TO ENABLE REPAIR. INCLUDING PRESSURIZE COOLING SYSTEM.	New	150.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,380.00</b>	<b>1,970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >