

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012981/KCP3E2**Date:** 26/07/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00233162205

**Claimant Vehicle
No :** SKH713D**Insured Vehicle
No :** SLN2256A

Date of Loss: 26/12/2022

Nature of Claim: TP

Claim
No: SNM22D209322/C02/LEEPGDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKH713D**

Make & Model: BMW 116D, 1.5 D 5DR HATCH DSC LED (A)

Engine No: 33949525B37D15A

Reg. Date: 08/04/2016 (Man. Year: 2016)

Chassis No: WBA1V72030V724308

Colour: Metallic Black

Odometer: 166740 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R17

Rear Tyre Size: 225/45Z R17

Front Left Side: OTANI 7 mm

Rear Left Side: OTANI 7 mm

Front Right Side: OTANI 7 mm

Rear Right Side: OTANI 7 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 5,857.65 | 1,564.15 | 4,293.50 | 73.30 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,000.00 | 500.00 | 1,500.00 | 75.00 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 7,857.65 | 2,064.15 | 5,793.50 | 73.73 |
| Approved Total (Overridden) (S\$) | | 1,600.00 | | |
| (S\$) | 7,857.65 | 1,600.00 | 6,257.65 | 79.64 |
| + GST 8.00/8.00% (S\$) | 628.61 | 128.00 | 500.61 | 79.64 |
| Nett Amount (S\$) | 8,486.26 | 1,728.00 | 6,758.26 | 79.64 |

INSPECTION

Date of Assignment: 29/12/2022

Date Inspected: 29/12/2022 Inspected At:

Thiam Heng Huat Pte Ltd (SIN MING)
176 SIN MING DRIVE, #05-14
Singapore 575721

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 26 Jul 2023) |
| Parts: | 144 | BMW 116D 1.5 D 5DR HATCH DSC LED (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SKH713D) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *TAILGATE | Repair | 1,563.00 FL | *- FL |
| 2 | 1 | | *TAILGATE WEATHERSTRIP | Serviceable | 289.00 FL | *- FL |
| 3 | 2 | | *REAR BUMPER REFLECTOR | Serviceable | 462.00 FL | *- FL |
| 4 | 1 | | *REAR BUMPER | Buckled | 1,295.00 FL | *1,295.00 FL |
| 5 | 1 | | *REAR BUMPER TOW HOOK COVER | Serviceable | 59.00 FL | *- FL |
| 6 | 2 | | *REAR BUMPER SIDE RETAINER | Serviceable | 370.00 FL | *- FL |
| 7 | 1 | | *REAR BUMPER REINFORCEMENT | Repair | 615.00 FL | *- FL |
| 8 | 2 | | *REAR BUMPER REINFORCEMENT BRACKET | Repair | 292.00 FL | *- FL |
| 9 | 1 | | *REAR BUMPER CENTER CARRIER | Cracked | 282.00 FL | *282.00 FL |
| 10 | 4 | | *REVERSE SENSOR HOLDER | Not Necessary | 56.00 FS | *- FS |
| 11 | 4 | | *REVERSE SENSOR (FACTORY ORIGINAL) | Serviceable | 720.00 FS | *- FS |
| 12 | 12 | | *REAR BUMPER CLIPS | Necessary | 66.00 FS | *66.00 FS |
| 13 | 1 | | *SUNDRIES | Not Necessary | 50.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 6,119.00 | 1,643.00 |
| - List Item Discount on L Items 5.00/5.00% (\$\$) | 261.35 | 78.85 |
| Total Parts (\$\$) | 5,857.65 | 1,564.15 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTION. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS | New | 1,000.00 | 220.00 |
| 2 | TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS | New | 100.00 | 60.00 |
| 3 | SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA / PANEL | New | 800.00 | 220.00 |
| 4 | TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR | New | 100.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 2,000.00 | 500.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >