

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012952/KQP3Q2**Date:** 27/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00265062201		
Claimant Vehicle No :	SDD727T	Insured Vehicle No :	SML5983M		
Date of Loss:	21/12/2022	Nature of Claim:	TP	Claim No:	SNM22D209177/C03/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDD727T	Engine No:	P520235015
Make & Model:	MAZDA 3, 1.5 SEDAN L SP.6EAT (A)	Chassis No:	JM6BM42A8F0151076
Reg. Date:	23/10/2014 (Man. Year: 2014)	Odometer:	96925 km
Colour:	Metallic Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,351.75	3,070.40	1,281.35	29.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	1,520.00	700.00	31.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,571.75	4,590.40	1,981.35	30.15
Approved Total (Overridden) (S\$)		3,650.00		
(S\$)	6,571.75	3,650.00	2,921.75	44.46
+ GST 8.00/8.00% (S\$)	525.74	292.00	233.74	44.46
Nett Amount (S\$)	7,097.49	3,942.00	3,155.49	44.46

INSPECTION

Date of Assignment:	12/02/2023	
Date Inspected:	30/12/2022	Inspected At: Ah Lim Motor Company (Sin Ming) 176 Sin Ming Drive #05-12, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2023)
Parts:	143	MAZDA 3 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDD727T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER LH	Bent	1,233.10 FL	*1,233.10 FL
2	1		*TAIL LAMP PANEL LH	Repair	396.70 FL	*- FL
3	1		*TAILAMP LH	Mtg Cracked	534.90 FL	*534.90 FL
4	1		*REAR BUMPER	Bent	1,138.60 FL	*1,138.60 FL
5	2		*REAR BUMPER SIDE RETAINER LH/RH	Cracked (1 PCS ONLY)	76.00 FL	*38.00 FL
6	15		*REAR BUMPER CLIP	Necessary	45.00 FL	*45.00 FL
7	1		*REAR BUMPER REFLECTOR LH	Broken	53.00 FL	*53.00 FL
8	1		*REAR BUMPER WHEEL SPLASH SEAL LH	Serviceable	83.20 FL	*- FL
9	1		*TAIL END PANEL	Repair	530.40 FL	*- FL
10	1		*REAR FENDER AIR VENT LH	Serviceable	74.90 FL	*- FL
11	1		*REAR BUMPER TOWING COVER	Missing	36.40 FL	*36.40 FL
12	1		*REVERSE LAMP LH	Serviceable	278.30 FL	*- FL
13	1		*REAR WINDSCREEN MOULDING	Necessary	77.00 FL	*77.00 FL
14	1		*SET REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
15	2		*WINDSCREEN SEALANT	Necessary	30.00 FS	*30.00 FS
					Sub Total (\$\$)	4,807.50 3,386.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	455.75 315.60
					Total Parts (\$\$)	4,351.75 3,070.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	20.00	20.00
2	TO DISMANTLE AND INSTALL REAR WINDSCREEN	New	120.00	120.00
3	TO DISMANTLE AND INSTALL REAR BOOT INNER TRIM COVER ,REAR SEAT AND SEAT BELT	New	80.00	80.00
4	TO DISMANTLE AND REPLACE DAMAGE PARTS .TO CUT AND WELD REAR FENDER LH ,KNOCK AND REPAIR REAR CABIN FLOOR PANEL AND AFFECTED AREA	New	1,150.00	700.00
5	TO SPRAY REAR FENDER LH ,REAR BUMPER ,TAIL END PANEL AND APPLY SEALANT	New	850.00	600.00
Gross Labour Cost (S\$)			2,220.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >