



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## OPINION ON REPAIR COST FOR VEHICLE NO. SG 5182M

Qty	Description of Parts	Condition	Recommended (\$)
<b>REPLACEMENT OF PARTS</b>			
2	LED LICENSE PLATE LAMP @\$21.00 (CONSISTENT)	DISTORTED	42.00
1	NUMBER PLATE RECESS PAN;EXT.RR (CONSISTENT)	BENT	168.00
1	RUBBER BUFFER;EXTERIOR REAR (CONSISTENT)	CUT	48.00
			258.00
<b>SPECIAL NETT ITEMS</b>			
1	SIKAFLEX 255 EXTRA BLACK (400ML/SAU) (SN) (CONSISTENT)	NECESSARY	12.50
1	POLYESTER PUTTY KANDE (2.5LT) (SN) (CONSISTENT)	NECESSARY	17.50
			30.00
<b>LABOUR</b>			
	PANEL.REAR BUMPER.O/S.		160.00
	SPRAY PAINT-GREEN;600ML;SG BUS.		30.00
	TO REMOVE / REPLACE / REPAIR DAMAGE PARTS / ASSESSMENT BY WORKSHOP.		188.00
	TO REMOVE / REPLACE / REPAIR DAMAGE PARTS BY CONTRACTOR.		750.00
	TO REMOVE / REPLACE / REPAIR DAMAGE ADVERTISEMENT/GREEN LIVERY PANEL.		100.00
			1,228.00
<b>GRAND TOTAL</b>			<b>1,516.00</b>
<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)</b>			<b>1,516.00</b>

Report Ref No. CS/ASM22012985/Tnp3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.