

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC22012987/Sny3e2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555		Date:	12/01/2023	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XE 1168H	Veh. Inspected		SMS 802Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/22/22/VC05/026576	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		29/12/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI I30	c.c		1353	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	TMAH3513VJJ062219	Colour		GREY	
	Odometer	86878 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/45 R17	MICHELIN		6 mm	
	L/H Front Tyre	225/45 R17	MICHELIN		6 mm	
	R/H Rear Tyre	225/45 R17	MICHELIN		6 mm	
	L/H Rear Tyre	225/45 R17	MICHELIN		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	JSTAINED DAMAGES AT THE N/S BODY.				
5.	General Information					
	Accident Date	14/11/2022	Inspect Date /	Time	03/01/2023 (03:00 PM)	
	Survey held at	GARAGE 13 PTE LTD				
		8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22012987/Sny3e2

Inspected By

S MOHAMED IRFAN BIN MOHAMED IQUBAL

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 ${\tt BEng(Hons),B.Bus,MBA,PEng,PE,\,MInstAEA,MASME,MIRTE}$

REGD Auto Consultant-SAE, Licensed Appraiser