

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S2M04BY0 Date: 10th Jan 2023

Our Ref: CS3/ASM22009652/Kwy3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01 Axa Tower Singapore 068811 (The Motor Claims Department)

Attn: Oh Vale

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMD 8924G

INSURED VEHICLE: SHA 3960J ACCIDENT DATE: 27/09/2022

We thank you for your instruction on 27/12/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMD 8924G from M/s Auto Consultants.
- b) Singapore Accident Statement of Vehicles SMD 8924G and SHA 3960J.
- c) Final Repair Bill of SMD 8924G from M/s Astute Autoworks Pte Ltd.
- d) Colour damaged vehicle photographs of SMD 8924G.

Pre-Repair Inspection Date: 30/09/2022 at M/s Astute Autoworks Pte Ltd, 60 Jalan Lam Huat #02-16/17, Carros Centre, Singapore 737869.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SMD 8924G

Make & Model : Mitsubishi Lancer 2.0L Mivec GT 6-CVT

Year of Registration : 2008

Chassis Number : JMYSTCY4A8U004758

Engine Capacity : 1998 cc

- 2. We recommend that the repairs of the entire damage require about <u>6 (Six)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.