



Auto Consultants

Co.Reg no: 53439395X

VEHICLE INSPECTION REPORT

Our Ref: SLVDIR/22/10/001

Date: 30/11/2022

To: ONG TECK WEI GARRICK
Repairer Company: ASTUTE AUTOWORKS PTE LTD
Address: 60 Jln Lam Huat, Carros Centre, #02-16/17
Postal Code: 737869

REFERENCES

Claim Type:	THIRD PARTY	Date of Accident:	27/09/2022
Third party vehicle:	SMD8924G	Date of Inspection:	03/10/2022
Insured Vehicle:	NIL		

DAMAGED VEHICLE PARTICULARS

Registration Plate No:	SMD8924G	Engine Modification:	NIL
Model/ Make:	Mitsubishi Lancer 2.0L Mivec	Pre-accident damage:	NIL
Date of Registration:	6/11/2008	General Condition:	Fair
Chassis No:	JMYSTCY4A8U004758	General Paint Colour:	White
Engine No:	4B11BR9116	Steering:	Good
Engine Capacity:	1998cc	Handbrake:	Good
Odometer No:	210353	Footbrake:	Good

TYRES CONDITION

Front Right

Make: Nexen
Size: 205 55 R17 60%

Front Left

Make: Nexen
Size: 205 55 R17 60%

Rear Right

Make: Dunlop
Size: 205 55 R17 50%

Rear Left

Make: Dunlop
Size: 205 55 R17 50%

The above percentages represent the remaining life of tyre treads

SL Auto Consultants

Accident Claims . Survey Services . Professional Advice

Add: 129 Lorong Ah Soo #05-352 Singapore 530129

Email: slautoconsultants@gmail.com / Mobile No: 90067276

VEHICLE REPAIR COST

Descriptions	Repairer SGD	Adjuster SGD
Parts	\$ 16,016.40	\$ 14,598.00
Special Nett	\$ 2,150.00	\$ 770.00
Labour	\$ 5,180.00	\$ 4,330.00
Calculated Cost SGD	<u>\$ 23,346.40</u>	<u>\$ 19,698.00</u>

Recommended Lump Sum Repair Cost SGD

\$ 15,758.40

Estimate Repair Duration

9 Working Days

Survey Inspection Location

ASTUTE AUTOWORKS PTE LTD

Survey Inspection Address

**60 Jln Lam Huat, Carros Centre, #02-16/17
Singapore 737869**

DESCRIPTION OF DAMAGE

Front Portion and LHS undercarriage

REMARKS

We have inspected the actual damages found on the vehicle and recommended the replacement of parts and repairs accordingly. The estimated repair cost is \$23,346.40. The repairer has to agree to undertake the repairs at our adjusted lump sum amount of \$15,750.00.

We have not authorized the repair. Under normal circumstances, estimated 9 working days are required.

We are pleased to advise that the inspection work was carried out accordingly and hereby submit our Inspection Report.

The inspection was conducted on a "WITHOUT PREJUDICE" basis.



Automotive Appraiser: Samuel Phun

SL Auto Consultants
Accident Claims . Survey Services . Professional Advice
Add: 129 Lorong Ah Soo #05-352 Singapore 530129
Email: slautoconsultants@gmail.com / Mobile No: 90067276

ASSESSMENT REPORT FOR VEHICLE NO: SMD8924G

LIST ITEMS

No	Qty	Description	CONDITION	REPAIRER Amount SGD	ADJUSTER Amount SGD
1	1	Front Bonnet	Bent	\$ 980.00	\$ 980.00
2	1	Front Bonnet Rubber	Necessary	\$ 68.00	\$ 68.00
3	1	Front Bonnet Insulator	Torn	\$ 380.00	\$ 380.00
4	2	Front Bonnet Hinges	Bent	\$ 180.00	\$ 180.00
5	1	Front Bonnet Lock	Bent	\$ 188.00	\$ 188.00
6	1	Front Bumper	Cracked	\$ 960.00	\$ 960.00
7	2	Front Bumper Side Retainer	Necessary	\$ 90.00	\$ 90.00
8	1	Front Bumper Reinforcement	Dented	\$ 498.00	\$ 498.00
9	1	Front Bumper Sponge	Cracked	\$ 180.00	\$ 180.00
10	1	Front Bumper Lower Grille	Cracked	\$ 220.00	\$ 220.00
11	1	Front Bumper Tow Cover	Deformed	\$ 48.00	\$ 48.00
12	2	Front Bumper Fog Lamp	LHS Cracked/ RHS Serviceable	\$ 688.00	\$ 344.00
13	2	Front Bumper Fog Lamp Cover	LHS Grazed/ RHS Serviceable	\$ 188.00	\$ 94.00
14	1	Front Bumper Top Beam	Bent	\$ 188.00	\$ 188.00
15	1	Front Bumper Top Beam Rubber	Necessary	\$ 88.00	\$ 88.00
16	2	Front Bumper Bracket	Necessary	\$ 180.00	\$ 180.00
17	1	Front Bumper under Cover	Cracked	\$ 180.00	\$ 180.00
18	1	Radiator Grille	Cracked	\$ 480.00	\$ 480.00
19	1	Radiator Grille Logo	Necessary	\$ 88.00	\$ 88.00
20	1	Radiator Grille Chrome Moulding	Cracked	\$ 240.00	\$ 240.00
21	2	Head Lamp	Cracked	\$ 2,160.00	\$ 2,160.00
22	2	Head Lamp Support Panel	LHS Bent/ RHS Repair	\$ 240.00	\$ 120.00
23	1	Support Panel Top Garnish	Deformed	\$ 120.00	\$ 120.00
24	1	Support Panel	Dented	\$ 588.00	\$ 588.00
25	1	Side Member Extension LHS	Dented	\$ 88.00	\$ 88.00
26	1	Air Con Condenser	Bent	\$ 1,234.00	\$ 1,234.00
27	1	Radiator	Dented	\$ 1,324.00	\$ 1,324.00
28	1	Fan Cowling	Cracked	\$ 488.00	\$ 488.00
29	1	Wiper Garnish	Cut	\$ 388.00	\$ 388.00
30	1	Fuse Box	Cracked	\$ 680.00	\$ 680.00
31	2	Fender	LHS Bent/ RHS Repair	\$ 1,440.00	\$ 720.00
32	1	Fender Bracket LHS	Necessary	\$ 28.00	\$ 28.00
33	2	Fender Inner Shield	Cracked	\$ 376.00	\$ 376.00
34	1	Fender Corner Garnish LHS	Necessary	\$ 80.00	\$ 80.00
35	1	Fender Signal LHS	Serviceable	\$ 78.00	\$ -
36	1	Front LHS Shock Absorber Top Mounting	Affected	\$ 180.00	\$ 180.00
37	1	Front LHS Shock Absorber	Distorted	\$ 488.00	\$ 488.00
38	1	Front LHS Knuckle Arm	Distorted	\$ 588.00	\$ 588.00
39	1	Front LHS Wheel Bearing	Affected	\$ 120.00	\$ 120.00
40	1	Front LHS Wheel Bearing Hub	Distorted	\$ 288.00	\$ 288.00
41	1	Front LHS Lower Arm	Distorted	\$ 488.00	\$ 488.00
42	1	Front LHS Anti Low Bar Link	Serviceable	\$ 220.00	\$ -
Sub-total				\$ 17,796.00	\$ 16,220.00
Less 10%				\$ 1,779.60	\$ 1,622.00
Total				\$ 16,016.40	\$ 14,598.00

SL Auto Consultants

Accident Claims . Survey Services . Professional Advice

SPECIAL NETT

1	Bonnet Insulator Clip Set	Necessary	\$ 60.00	\$ 40.00
2	Bumper Clip Set	Necessary	\$ 60.00	\$ 40.00
3	Support Panel Top Gamish Clip Set	Necessary	\$ 60.00	\$ 30.00
4	Bumper Side Lower Spoiler Set	Cracked	\$ 600.00	\$ 500.00
5	Fender Inner Shield Clip Set	Necessary	\$ 120.00	\$ 80.00
6	Front LHS Sport Rim	Serviceable	\$ 800.00	-
7	Front LHS Tyre	Serviceable	\$ 300.00	-
8	Horn	Dented	\$ 150.00	\$ 80.00
Sub-total			\$ 2,150.00	\$ 770.00

LABOUR

1	To change and balancing front LHS rim and tyre	\$ 60.00	\$ 40.00
2	To check wiring and focus head lamp setting	\$ 150.00	\$ 120.00
3	To replace radiator and perform pressure leak test	\$ 100.00	\$ 80.00
4	To apply anti rust proofing on affected areas	\$ 150.00	\$ 80.00
5	To perform wheel alignment test	\$ 120.00	\$ 80.00
6	To replace a/c condenser and top up gas system to assist repair	\$ 120.00	\$ 100.00
7	To perform diagnostic check for fault code and reset factory settings	\$ 300.00	\$ 180.00
8	To remove, replace and refix front LHS under carriage damaged parts	\$ 380.00	\$ 250.00
9	To panel beat and replace damaged parts on affected areas	\$ 1,800.00	\$ 1,600.00
10	To putty and spray painting on affected areas	\$ 2,000.00	\$ 1,800.00
Sub-total		\$ 5,180.00	\$ 4,330.00
Total cost		\$ 23,346.40	\$ 19,698.00