



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNC 8056E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR RH FENDER	TO REPAIR SEE LABOUR	2,513.00	-
1	REAR RH DOOR	TO REPAIR SEE LABOUR	2,626.00	-
1	REAR RH TYRE	SERVICEABLE	480.00	-
			5,619.00	-
	<u>SPECIAL NETT ITEMS</u>			
1	REAR RH TYRE RIM (SN)	CUT	650.00	650.00
			650.00	650.00
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACE DAMAGED PARTS, PANELBEAT WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF REAR RH FENDER AND REAR RH DOOR.		450.00	400.00
	TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE CHANGE OF REAR FENDER.	NOT NECESSARY	150.00	-
	TO TRANSFER DOOR COMPONENTS.	NOT NECESSARY	60.00	-
	TO PUTTY, APPLY PRIMER & SPRAYPAINT REAR RH DOOR AND FENDER AND REAR BUMPER.		900.00	700.00
	TO APPLY RUSTPROOFING ON REPAIRED, REPLACED PANEL.	NOT NECESSARY	120.00	-
			1,680.00	1,100.00
GRAND TOTAL			7,949.00	1,750.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,400.00

Report Ref No. CS/SPF22012991/Uny3m4

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,400-\$1,600

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.