

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 6911P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	CUT	1,855.30	1,300.00
1	REAR BUMPER (LOWER) (CONSISTENT)	CUT	630.00	320.00
1	REAR BUMPER SIDE RETAINER LH (CONSISTENT)	NOT NECESSARY	82.40	-
1	REAR BUMPER REFLECTOR LH (CONSISTENT)	BROKEN	110.50	95.00
1	REAR BUMPER CENTRE FRAME (CONSISTENT)	NOT NECESSARY	280.30	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	620.00	-
1	REAR BUMPER SENSOR (CONSISTENT)	CRACKED	280.30	280.30
1	TAIL LAMP LH (CONSISTENT)	BROKEN	622.40	470.00
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	820.50	-
	LESS 10% DISCOUNT		-530.17	-246.53
			4,771.53	2,218.77
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	REAR END PANEL INSULATION SEAL (SN) (CONSISTENT)	NOT NECESSARY	120.00	-
			140.00	20.00
	<u>LABOUR</u>			
	PANEL BEATING ,REMOVAL AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT AND REAR END PANEL.		1,200.00	600.00
	TO SPRAY PAINT AFFECTED AREA .		1,200.00	500.00
	TUFF COAT.	NOT NECESSARY	250.00	-
	WIRING CHECK.		80.00	50.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	30.00
			2,810.00	1,180.00
	GRAND TOTAL		7,721.53	3,418.77

Report Ref No. CC4/ASM22012994/Spa3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,750.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM22012994/Spa3q2

1/

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

Amont

HO LEONG CHUAN

Automotive Assessor