

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22012995/GPA3Q2**Date:** 18/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070118268
Claimant Vehicle No :	SMQ8597Z	Insured Vehicle No :	SMU5077G
Date of Loss:	26/12/2022	Nature of Claim:	TP
		Claim No:	8538698569SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ8597Z		
Make & Model:	MERCEDES-BENZ GLA180 URBAN (R18 LED), 1.6 (A)	Engine No:	27091031920962
Reg. Date:	05/12/2019 (Man. Year: 2019)	Chassis No:	WDC1569422J667076
Colour:	Black	Odometer:	30334 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,878.90	4,777.70	2,101.20	30.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,330.00	1,140.00	1,190.00	51.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,208.90	5,917.70	3,291.20	35.74
+ GST 8.00/8.00% (S\$)	736.71	473.42	263.29	35.74
Nett Amount (S\$)	9,945.61	6,391.12	3,554.49	35.74
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		6,657.87		

INSPECTION

Date of Assignment:	29/12/2022	
Date Inspected:	29/12/2022	Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LOGO	Necessary	81.00 FL	*81.00 FL
2	1		*TAILGATE EMBLEMN	Necessary	115.00 FL	*115.00 FL
3	1		*REAR BUMPER	Deformed	1,531.00 FL	*1,228.00 FL
4	2		*REAR BUMPER SIDE RETAINER	Not Necessary	196.00 FL	*- FL
5	1		*REAR BUMPER LUGGAGE SCUFF PLATE	Necessary	426.00 FL	*426.00 FL
6	1		*REAR BUMPER CENTRE GARNISH	Defaced	917.00 FL	*560.00 FL
7	1		*REAR BUMPER DIFFUSER	Broken	1,358.00 FL	*1,043.00 FL
8	1		*REAR BUMPER TOW HOOK COVER	Repair	175.00 FL	*- FL
9	1		*O/S REAR SILENCER CHROME	Scratched	393.00 FL	*393.00 FL
10	1		*O/S REAR SILENCER CHROME BRACKET	Broken	164.00 FL	*164.00 FL
11	1		*REAR BUMPER REINFORCEMENT	Bent	943.00 FL	*943.00 FL
12	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	242.00 FL	*- FL
13	1		*REAR BUMPER CENTER BRACKET	Not Necessary	176.00 FL	*- FL
14	1		*O/S REAR BUMPER LOWER BRACKET	Not Necessary	128.00 FL	*- FL
15	1		*REAR BUMPER LOWER STIFFENER	Not Necessary	158.00 FL	*- FL
16	1		*O/S REAR BUMPER CENTRE GARNISH BRACKET	Not Necessary	118.00 FL	*- FL
17	1		*REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
18	1		*REAR BUMPER RIVET	Necessary	80.00 FS	*20.00 FS
19	1		*REVERSE SENSOR	Not Working	250.00 FS	*250.00 FS
20	1		*REAR WHEEL ARCH GARNISH CLIPS	Necessary	80.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,591.00	5,273.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	712.10	495.30
Total Parts (\$\$)	6,878.90	4,777.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	0.00
2	TO FIT REVERSE SENSOR IN BUMPER	New	50.00	40.00
3	TO RESET CLEARANCE SONAR USING DIAGNOSTIC SCANNER	New	250.00	0.00
4	TO RUST PROOF PANELS	New	180.00	0.00
5	TO REMOVE /REFIT /RE-ALIGN REAR SILENCER	New	200.00	0.00
6	TO REPAIR INNER PANEL ACCIDENT DAMAGE AREA,REPLACEMENT OF PARTS AND ALIGN THE SAME	New	700.00	400.00
7	TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA	New	900.00	700.00
Gross Labour Cost (S\$)			2,330.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >