

GARAGE 13 PTE LTD

8 KAKI BUKIT AVE 4 #02-54/55 PREMIER@KB SINGAPORE 415875

UEN GST REG NO: 202005684D

Date

7/11/2022

Proforma Ref No: G13/30233

To

EVEREST LEASING PTE LTD

Vehicle No

GBG7603D

Accident Date: 19/5/2022

	PROFORMA INV	OICE	
	Description		Amount
Repair Cost			\$ 6,500.00
		Sub-Total	 6,500.00
		GST 7%	\$ 455.00
		TOTAL	\$ 6,955.00

Payment by cheque should be crossed and made payable to 'Garage 13 Pte Ltd'

Issued By:

Authorised Signature

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: 6385 1171

Our reference:

22 - 170715

Date:

31/05/2022

INVOICE NO.

170715

Everest Leasing Pte Ltd c/o Garage 13 Pte Ltd 8 Kaki Bukit Ave 4 #02-55 Premier@KB Singapore 415875

Registration No.

GBG7603D

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	A	mount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$	625.00
	Total am	ount	\$	625.00

Please kindly cross all cheques made payable to "Impact Analysis Consulting Pte Ltd".

We thank you in anticipation for your prompt payment.

2

L. L. Tan (Ms)
Principal Consultant

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: 6385 1171

Our reference:

22 - 170715

Date:

31/05/2022

c/o Garage 13 Pte Ltd 8 Kaki Bukit Ave 4 #02-55 Premier@KB Singapore 415875

Dear Sirs

RE:

Road Traffic Accident on 19-05-2022

Everest Leasing Pte Ltd

In accordance with your instructions received in this office on

19-05-2022 , we made arrangements to

examine the vehicle on

19-05-2022

at above-mentioned address. The following data was

recorded:

Vehicle details


Make	Volkswagen	Registration	GBG7603D
Model	Caddy	Chassis	WV1ZZZ2KZHX093675
Colour	Blue	Gearbox	Auto
Odometer	66665km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

Tyre Depths

Front left	195/65R15	85% Kapsen
Front right	195/65R15	85% Kapsen
Rear left	195/65R15	85% Hankook
Rear right	195/65R15	85% Hankook

Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$6,500.00 and 7 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: 6385 1171

Our reference:

22 - 170715

Date:

31/05/2022

Page

2

WV12222K2HX0936X

Section A: Damaged Parts Assessment

Section A. Dan	lageu	raits Assessinelit		
Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment
<u>List Items</u> :				910
Rear bumper	1	deformed	1448.90	1448.90
Rear bumper side retainer @\$69.20	2	broken	138.40	138.40
Rear bumper reinforcement	1	distorted	558.60	558.60
Rear bumper center guide bracket	1	deformed.torn	225.00	225.00
Rear bumper reflector @\$85.50	2	rh missing Ih holder broken	171.00	171.00
Rear door Ih	1	distorted	2345.10	2345.10 1950
Rear door rh - slightly bent	1	repair.respray	1985.40	0.00
Tailgate hinges @\$78.80	4	check.refix	315.20	0.00
Tailgate lock lower @\$211.50 PH NH NW	2	misaligned.bent	423.00	423.00 211.50
Tailgate lock regulator	1	malfunction	325.00	325.00
Tail lamp @\$412.90	2	refix	825.80	0.00 /
Rear end panel Rey	1	distorted	621.50	621.50
Tailgate "TDI" emblem	1	necessary	72.00	72.00
Tailgate "VW logo" emblem	1	necessary	85.00	85.00
Tailgate "CADDY" emblem	1	necessary	78.50	78.50
S	ub- To	tal cost	9618.40	6492.00
Percentage disc	ount:	10%	961.84	649.20
Sub-To	otal co	sts for parts	8656.56	5842.80
Special Nett Items:				
Rear bumper clips	1set	necessary	50.00	50.00
Rear bumper reverse sensor	2	cracked.malfunction	250.00	250.00 200
Tailgate "70km/h" sticker	1	necessary	15.00	15.00
Rear door windscreen glass sealant Ih	1	necessary	40.00	40.00
Rear door windscreen glass sealant rh	1	not nec	40.00	0.00 +
Rear end panel sealant	1	necessary	40.00	40.00
	otal cos	sts for parts	435.00	395.00
Parts Repair				
*	*	*	0.00	0.00
Si	ıb- Tot	al costs	0.00	0.00
		for parts =	9091.56	6237.80
1.000		■ 14 10 M ■ 27 05 2 5 7 7 1		

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: **6385 1171**

Our reference:

22 - 170715

Date:

31/05/2022

Page

3

Section B: Labour Cost Calculation

T- "	Hourly rate	Manhr. Req.	Total	
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 45.00	19	\$	855,00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-con	tract work.	\$	700.00
Apply rust proofing on the adjacent panels.	Sub-con	tract work.	\$	50.00
Conduct water leak test for rear portion associated repair works	\$ 45.00	1	\$	45.00
Transfer of existing rear door mechanism to new door lh.	\$ 45.00	1.8	\$	81.00
Remove and refix rear door windscreen glass Ih.	\$ 45.00	2	\$	90.00
Remove and replace rear reverse sensor	\$ 45.00	1.7	\$	76,50
Wiring / bulb checking (inclusive of re-focus / re-adjust on angle of light intensity.)	\$ 45.00	0.7	\$	31.50
To		Total labour cost		,929.00

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

1462.50

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: 6385 1171

Date:

31/05/2022

Section C: Summary Table of Total Repair Cost

Description	Cost
Damaged Parts Assessment (See section A)	\$6,237.80
Labour Cost Calculation (See section B)	\$1,929.00
Total cost	\$8,166.80
Lump sum repair	
Further discount 20%	\$1,633.36
Total Repair Cost	\$6,500.00

<i>\$6,500.00</i> and	7 working days for repair.
out our expressed written agreemen	t. Any significant additional
ry report.	
The Table and the second of th	
	tolel: 5763.50
ness, Licensed Appraiser (Automobile)	(0006. 2162.20
	95:461c.
ore (#20100091)	
	l .
	D.C.
	05 Days.
ation for Management Consultants	
֡֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜	out our expressed written agreemen

IMI Professional Certificate In Vehicle Accident Damage Assessment (UK)