

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG22012998/AVP3E2**Date:** 28/03/2023**REFERENCE**

Insured/Claimant:	LIM ANN NA	Policy No:	1700063065-05	
Date of Loss:	22/12/2022	Nature of Claim:	OD	Claim No: 6936060157SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFP6009G		
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Engine No:	CVK047200
Reg. Date:	10/10/2017 (Man. Year: 2017)	Chassis No:	WAUZZZF5XJA034458
Colour:	Black	Odometer:	42448 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$130,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,791.00	8,307.60	24,483.40	74.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,372.00	2,772.00	3,600.00	56.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,163.00	11,079.60	28,083.40	71.71
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	38,363.00	10,279.60	28,083.40	73.20
+ GST 8.00/8.00% (S\$)	3,069.04	822.37	2,246.67	73.20
Nett Amount (S\$)	41,432.04	11,101.97	30,330.07	73.20

INSPECTION

Date of Assignment:	30/12/2022	
Date Inspected:	29/12/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,493.00 FS	*1,994.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	425.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Cracked	219.00 FS	*174.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	254.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	144.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	2,576.00 FS	*2,060.80 FS
8	2		*FRONT PARKING AID SENSOR SUPPORT - LH / RH	Not Necessary	116.00 FS	*- FS
9	1		*RADIATOR GRILLE COVER - UPPER	Not Necessary	209.00 FS	*- FS
10	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	1,058.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Deformed	139.00 FS	*110.80 FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	899.00 FS	*719.20 FS
13	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	82.00 FS	*- FS
14	1		*FRONT BUMPER TOP COVER	Cracked	143.00 FS	*114.00 FS
15	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*13.28 FS
16	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*7.12 FS
17	1		*LOCK CARRIER BRACKET	Cracked	154.00 FS	*130.00 FS
18	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	64.00 FS	*- FS
19	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	531.00 FS	*- FS
20	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
21	1		*SET FRONT BUMPER WIRING	Not Necessary	567.00 FS	*- FS
22	1		*HORN HIGH TONE - LH	Not Necessary	134.00 FS	*- FS
23	1		*HORN LOW TONE - RH	Not Necessary	139.00 FS	*- FS
24	2		*HORN BRACKET - LH / RH	Not Necessary	66.00 FS	*- FS
25	1		*BONNET	Dented	3,491.00 FS	*2,792.80 FS
26	1		*BONNET IMPACT PROTECTION - CENTER / LH / RH (3PCS)	Necessary	93.00 FS	*80.00 FS
27	2		*BONNET STRIKER - LH / RH	Not Necessary	112.00 FS	*- FS
28	2		*BONNET LOCK - LH / RH	Not Necessary	455.00 FS	*- FS
29	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
30	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
31	2		*HEADLIGHT - LH / RH	Not Necessary	16,832.00 FS	*- FS
32	2		*LIFT CYLINDER - LH / RH	Not Necessary	434.00 FS	*- FS
33	2		*LIFT CYLINDER BRACKET - LH / RH	Not Necessary	34.00 FS	*- FS
34	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	100.00 FS	*- FS
35	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	21.00 FS	*17.36 FS
36	2		*RADIATOR AIR GUIDE - LH / RH INNER	Deformed	72.00 FS	*29.84 FS
37	2		*RADIATOR AIR GUIDE - LH / RH OUTER	Not Necessary	38.00 FS	*- FS
38	2		*RADIATOR AIR GUIDE - LOWER / UPPER	Not Necessary	44.00 FS	*- FS
39	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
40	1		*SUNDRIES	Necessary	400.00 FS	*3.20 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 32,791.00 8,307.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	0.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	2,500.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
Gross Labour Cost (S\$)			6,372.00	2,772.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >